Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-641034
Estimate date:	11/03/2023
Customer:	Melody Pacheco
Phone:	
Insurance claim:	C-1436
Vehicle:	2019 Jeep Cherokee
VIN:	TKT5JMWZ3M82L5909
License plate:	Y56-03B

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$999.63
Trunk lid	1	$713.34
Rear bumper cover	1	$680.07
Body labor	27.6 hrs	$1,879.28
Paint and materials		$824.42
TOTAL		$5,096.74

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp assembly broken and the trunk lid edge pushed inward. The damage pattern is mostly consistent with the ipmact described, and the spot damage and crush depth match a rear-end strike at low speed. No earlier damage to the vehicle is known, and the prior repair records reviewed show no repeated charges. The planned repair covers replacing the bumper cover, the tail lamp, and reinforcement bar, with bodywork on the trunk lid edge and refinishing of the affected panels. The labor hours requested fit the damage shown and are reasonable for the scope of work.