King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-546344
Estimate date:	April 4, 2023
Customer:	Brandi Giles
Phone:	346-555-9081
Insurance claim:	C-1438
Vehicle:	2010 Kia Sorento
VIN:	
License plate:	073 9SP

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$317.57
Left front fender	1	$265.89
Front bumper cover	1	$175.33
Body labor	6.4 hrs	$435.62
Paint and materials		$273.47
TOTAL		$1,467.88

Appraiser remarks

Vehicle inspected at the body shop following a side impact at an intersection. The damage to the driver-side front door, rear quarter panel and adjacent sill is largely consistent with the reported collision geometry, and the pattern of crush and paint transfer matches the account given. Repair plan calls for door replacement, quarter panel repair and refinishing, with labor hours that fit the scope of the visible damage. The invoice history reviewed shows no repeated charges for the same work. Nothing in the file points to earlier damage on this vehicle in the affected areas. Recommend approval of the repair as presented.