Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-705123
Estimate date:	04/10/2025
Customer:	Tonya Compton
Phone:	832-555-8839
Insurance claim:	C-1440
Vehicle:	2015 Hyundai Elantra
VIN:	D785E4D047VT91216
License plate:	973102

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,105.20
Right tail lamp assembly	1	$753.27
Rear bumper reinforcement	1	$777.40
Body labor	30.1 hrs	$2,044.17
Paint and materials		$994.49
TOTAL		$5,674.53

Appraiser remarks

The rear bumper cover is cracked across the center with the left quarter panel creased near the taillight, and the trunk lid shows a shallow dent consistent with the reported impact. Some of the lower reinforcement damage could have come from this collision, but it is not clear whether all of it did, so the plan keeps those items flagged for a closer look once the panels are removed. The repair labor hours fit the damage described, and the plan clals for replacing the bumper cover, straightening the quarter panel, and refinishing the affected areas. No earlier damage to this vehicle is known from the file. The bills submitted show no repeated charges for the same work.