Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-950908
Estimate date:	5-22-25
Customer:	Brandon Hernandez
Phone:	713-555-9126
Insurance claim:	C-1441
Vehicle:	2015 Hyundai Elantra
VIN:	HKUP01PK74WD08885
License plate:	916 2907

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$603.27
Rear body panel	1	$471.33
Rear bumper cover	1	$265.15
Body labor	16.3 hrs	$781.80
Paint and materials		$384.91
TOTAL		$2,506.46

Appraiser remarks

The rear bumper cover is cracked across its center, and the tow hook bracket and trunk lid edge show crush consistent with a straight rear impact. Damage to the taillight housing and the surrounding quarter panel seam also lines up with the reported impact direction, so most of what is visible fits the account given. Repair plan is to replace the bumper cover, straighten the bracket, refinish the trunk lid edge and reinstall the lamp assembly. The labor hours on the estimate run somewhat high for this scope, so the shop should be asked to justify them. No earlier damage to this vehicle is known to us, and the invoices submitted show no repeated charges.