White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-502184
Estimate date:	February 3, 2023
Customer:	Justin Brown
Phone:	832-555-9819
Insurance claim:	C-1442
Vehicle:	2023 Chevrolet Malibu
VIN:	H4NESXSV4CVSX7037
License plate:	RB 3671

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$540.69
Front bumper cover	1	$370.80
Headlamp assembly	1	$399.85
Body labor	11.0 hrs	$746.85
Paint and materials		$448.18
TOTAL		$2,506.37

Appraiser remarks

The rear quarter panel on the driver's side shows a long dent with paint transfer along the edge, and the damage pattern lines up well with a sideswipe during a lane change. The rear bumper cover has a cracked corner and a scuffed mounting bracket. Several small scratches sit near the wheel arch, and some of these may be older than this crash, so they have been noted separately and are not included in the repair scope. Labor hours requested fit the extent of the work, and the repair plan calls for panel straightening, paint blending, and replacement of the bumper cover. The billing records reviewed show no repeated charges for the same operations.