Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-137038
Estimate date:	February 7, 2025
Customer:	Sarah Porter
Phone:	832-555-5027
Insurance claim:	C-1443
Vehicle:	2021 Toyota Camry
VIN:	C9ZNUWHEXFFS96048
License plate:	VUD-7506

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$529.37
Hood panel	1	$576.98
Left quarter panel	1	$458.26
Body labor	26.7 hrs	$1,281.62
Paint and materials		$535.03
TOTAL		$3,381.26

Appraiser remarks

The vehicle shows damage consistent with the reported parking lot impact, concentrated on the rear quarter panel and bumper cover, with the paint scuffing and clip breaks lining up with the described contact point. Repair will involve replacing the bumper cover, refinishing the quarter panel, and reinstalling the tail light assembly. The etsimated labor hours run slightly high for this scope, so a line-by-line review is recommended before approval. No prior damage to the vehicle is known, and the parts invoices show no repeated charges.