Mitchell Collision Center

7738 Leon Underpass Apt. 148
Baytown, TX
Phone 713-555-3433

Repair Estimate

Estimate number:	EST-186104
Estimate date:	11/12/2023
Customer:	Cynthia Marks
Phone:	346-555-3050
Insurance claim:	C-1444
Vehicle:	2011 Ford F-150
VIN:	0TF1D4YZ0G0HS3716
License plate:	UL 7981

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$995.14
Headlamp assembly	1	$838.91
Right front door shell	1	$1,132.30
Body labor	37.2 hrs	$2,529.79
Paint and materials		$1,330.67
TOTAL		$6,826.81

Appraiser remarks

The vehcile presents right-side damage consistent with a sideswipe during a lane change: the rear quarter panel has a long scrape with a crease running into the door skin, the side mirror housing is cracked, and the rear bumper cover has a scuffed corner. The damage pattern lines up with the impact as reported. Paint transfer and the direction of the body deformation support the same contact point. The repair plan clals for replacing the mirror housing, straightening and refinishing the quarter panel, and blending adjacent paint. The labor hours requested fit the extent of the work shown. No prior damage to this vehicle is known, and the parts and labor charges submitted contain no repeated entries.