Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-176051
Estimate date:	4-2-24
Customer:	Emily Miller
Phone:	281-555-2355
Insurance claim:	C-1446
Vehicle:	2021 Ford F-150
VIN:	GF1ZX8D142K571618
License plate:	LCV 261

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$286.60
Left quarter panel	1	$212.79
Left front fender	1	$148.81
Body labor	9.0 hrs	$432.28
Paint and materials		$242.63
TOTAL		$1,323.11

Appraiser remarks

The rear bumper cvoer is cracked across the left corner, with the tail lamp housing and left quarter panel showing matching scuffs and paint transfer, which fits the low-speed parking lot impact described. Replacement of the bumper cover and lamp assembly with refinishing of the quarter panel is the recommended plan. The labor hours on the etsimate run a little high for this scope, so the body shop has been asked to justify them line by line. Two similar charges entered on the same day are being verified before payment. No prior damage to this vehicle is known from the records reviewed.