Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-475151
Estimate date:	29 May 2023
Customer:	Allen Johnson
Phone:	281-555-5331
Insurance claim:	C-1447
Vehicle:	2018 Ford F-150
VIN:	5VD845VF87MAM3247
License plate:	6TT 739

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,243.59
Front bumper cover	1	$1,379.44
Left front fender	1	$803.00
Body labor	29.2 hrs	$1,986.06
Paint and materials		$1,431.57
TOTAL		$6,843.66

Appraiser remarks

The vehicle shows a deep crushed section along the driver side door and rear quarter panel, with a bent B-pillar and a cracked side window frame. The damage pattern lines up well with a side impact at an intersection, and the paint transfer and crush depth point to a signle strike rather than a series of events. The repair plan calls for replacing the front and rear doors, the quarter panel, and the rocker trim, followed by frame straightening and refinishing. The labor hours requested match the scope of the damage, and the parts invoices show no repeated charges. Nothing in the file suggests earlier damage to this vehicle.