Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-334977
Estimate date:	2024-09-26
Customer:	Jose Mercado
Phone:	713-555-4283
Insurance claim:	C-1449
Vehicle:	2013 Ford F-150
VIN:	ECL7M4T982PFF3344
License plate:	G 787335

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,949.38
Front bumper cover	1	$1,553.36
Right front door shell	1	$854.89
Body labor	37.5 hrs	$2,546.72
Paint and materials		$1,700.12
TOTAL		$8,604.47

Appraiser remarks

The vehicle presents front-end damage consistent with a low-speed head-on impact, centered on the bumper assembly, grille, and hood leading edge, with a cracked headlamp bracket and bent radiator support. Most of the visible deformation lines up with the reported event. The proposed repair plan calls for replacing the bumper cover, hood, and headlamp assembly, straightening the radiator support, and refinishing adjoining panels. The labor hours requested match the scope of this work. No prior damage to the vehicle is known from our records. Two similar charges submitted on the same day are currently under review before this estimate is finalized.