Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-864722
Estimate date:	5 Aug 2024
Customer:	Michele Henderson
Phone:	281-555-0388
Insurance claim:	C-1452
Vehicle:	2014 Toyota Camry
VIN:	4MWYKE6M0681W2279
License plate:	5-L0653

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,027.64
Right front door shell	1	$1,050.35
Front bumper cover	1	$897.79
Body labor	33.5 hrs	$2,280.08
Paint and materials		$1,260.74
TOTAL		$6,516.60

Appraiser remarks

Right rear quarter panel shows scuffing and a deep scrape running along the lower edge of the door, with a dented rear fender bead and cracked taillight lens on the same side. The damage pattern lines up with a side contact during a lane change, and the paint transfer and scrape height are consistent with the reported impact. Repair plan calls for panel replacement, blend and refinish of the adjacent panels, and lens replacement. Labor hours are reasonable for the scope described. Invoices from the shop show a single set of charges with no duplicated line items. No prior damage to this vehicle is on record.