Osborne Auto Body

870 Samantha Crossing
League City, TX
Phone 281-555-7889

Repair Estimate

Estimate number:	EST-458568
Estimate date:	19 Apr 2024
Customer:	Tracy Edwards
Phone:	
Insurance claim:	C-1453
Vehicle:	2021 Jeep Cherokee
VIN:	NHVN3E5T5CUUK8157
License plate:	68VT012

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,093.68
Rear body panel	1	$1,163.96
Rear bumper cover	1	$623.28
Body labor	34.8 hrs	$2,363.09
Paint and materials		$987.22
TOTAL		$6,231.23

Appraiser remarks

The rear bumper cover is cracked across its center, the tail lamp assembly on the driver side is broken, and the trunk lid shows a crease with paint loss aolng the upper edge. Part of the lower panel damage may have come from an earlier event, so it is not yet clear whether all of it stems from this impact. The labor hours listed fit the damage observed, and no prior damage to this vehicle is known to us. Two similar charges on the same day are being checked before the estimate is finalized. Plan: replace the bumper cover and tail lamp, repair and refinish the trunk lid, and inspect the lower panel once it is exposed.