Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-411121
Estimate date:	02/12/2024
Customer:	Gina Smith
Phone:	832-555-2986
Insurance claim:	C-1455
Vehicle:	2021 Nissan Altima
VIN:	08VMXAAZ56VJB0436
License plate:	8R B6919

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$742.01
Right front door shell	1	$587.06
Left front fender	1	$676.43
Body labor	27.9 hrs	$1,895.49
Paint and materials		$805.40
TOTAL		$4,706.39

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp housing is broken, with scuffing and paint transfer on the cover that lines up with the reported strike point. Damage to the left quarter panel and the trunk lid edge is consistent with a low-speed rear impact in a parking lot setting. The plan calls for replacing the bumper cover and tail lamp assembly, refinishing the rear panel, and recalirbating the parking sensor. The labor hours requested fit the scope of this work. Invoices on file show no repeated charges, and nothing in the vehicle's history indicates earlier damage to these components.