Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-632151
Estimate date:	12-2-24
Customer:	Nicole Mooney
Phone:	281-555-3616
Insurance claim:	C-1456
Vehicle:	2024 Jeep Cherokee
VIN:	FS0C2MVS5RTF82072
License plate:	WLZ-852

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$435.67
Front bumper cover	1	$252.26
Left front fender	1	$281.59
Body labor	13.5 hrs	$647.48
Paint and materials		$444.67
TOTAL		$2,061.67

Appraiser remarks

The front bumper cover on the vehicle is cracked across the left corner, with the left fog lamp bracket broken and the left fender edge scuffed and pushed inward. The pattern of the damage matches the impact described for a collision while turning left. Nothing on the car points to earlier damage in this area, and the repair bills submitted show no repeated charges. The proposed plan is to replace the bumper cover, fog lamp bracket and fender, then refinish and recalibrate the affected sensors. The labor hours on the estimate run a little high for this scope of work, so the shop should be asked to review them before approval.