Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-198957
Estimate date:	3-15-23
Customer:	Jose Conrad
Phone:	832-555-0142
Insurance claim:	C-1457
Vehicle:	2013 Kia Sorento
VIN:	NYUSWN6D7WVRA4344
License plate:	WWS 663

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$278.95
Rear body panel	1	$353.75
Right tail lamp assembly	1	$251.29
Rear bumper reinforcement	1	$278.95
Body labor	14.2 hrs	$683.70
Paint and materials		$352.06
TOTAL		$2,198.70

Appraiser remarks

The rear bumper cover is cracked and pusehd inward, the trunk lid edge is bent, and the left tail lamp assembly is broken, all consisetnt with the reported impact. No prior damage to this vehicle is known from the records reviewed. The proposed plan is to replace the bumper cover and tail lamp, repair the trunk lid, and refinish the rear panel. The labor hours on the estimate run slightly high for this scope of work and should be checked against standard repair times before approval. A related service entry also appears twice for the same visit, and the shop acknowledged the second line was a repeat.