Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-752402
Estimate date:	10/24/2024
Customer:	Steve Kelly
Phone:	
Insurance claim:	C-1458
Vehicle:	2020 Ford F-150
VIN:	G1HUXXEC140WR8395
License plate:	HVM 314

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,490.06
Headlamp assembly	1	$1,337.45
Hood panel	1	$835.37
Body labor	33.1 hrs	$2,253.73
Paint and materials		$1,745.88
TOTAL		$7,662.49

Appraiser remarks

The vehicle arrived with crushed front bumper cover, cracked grille and a displaced hood latch, with the radiator support showing bending consistent with a frontal impact at low speed. Some of the lower damage may have come from this collision, but it is not yet clear whether all of it did, so the older-looking marks on the lower panels are being checked before final approval. The repair plan calls for replacing the bumper cover, grille, hood latch and radiator support, with refinishing of the front end and a scan for sensor faults. The labor hours listed fit the damage described. No earlier damage to the vehicle is known. Two similar charges on the same day are being checked against the file before payment is released.