Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-702143
Estimate date:	2023-05-15
Customer:	Douglas Randall
Phone:	281-555-1239
Insurance claim:	C-1459
Vehicle:	2010 Kia Sorento
VIN:	TXR7RRJN9WED83383
License plate:	47-U603

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$961.39
Left quarter panel	1	$1,051.31
Headlamp assembly	1	$852.93
Body labor	49.2 hrs	$2,363.43
Paint and materials		$1,150.70
TOTAL		$6,379.76

Appraiser remarks

The rear bumper cover on the vehicle is cracked and displaced on the driver's side, with the matching paint transfer and a dented quarter panel consistent with the reported impact. No earlier damage to the vehicle is known, and the pattern of deformation lines up with the way the collision was described. The proposed plan calls for replacing the bumper cover, refinishing the quarter panel, and recalibrating the parking sensors. The labor hours submitted run a little high for this scope of work, so I recommend a line-by-line review before approval. The invoices provided show no repeated charges.