Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-435216
Estimate date:	09/28/2023
Customer:	Kathryn Drake
Phone:	281-555-0621
Insurance claim:	C-1461
Vehicle:	2016 Hyundai Elantra
VIN:	FLLX2EN99BVS26273
License plate:	WOB6250

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$778.24
Headlamp assembly	1	$714.71
Hood panel	1	$548.77
Body labor	20.3 hrs	$1,377.85
Paint and materials		$858.92
TOTAL		$4,278.49

Appraiser remarks

The vehicle shows a sideswipe pattern along the right rear quarter panel, with scuffed paint, a dented rear door skin, and a cracked taillight lens on the same side. The damage lines up with the impact as it was described, and the panels affected are the ones you would expect from a contact while changing lanes. The repair plan clals for replacing the rear door skin, refinishing the quarter panel and door, and swapping the taillight assembly. The labor hours requested fit the scope of this work. The invoices submitted contain no repeated charges. No earlier damage to this vehicle is known from the records reviewed.