Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-934691
Estimate date:	2025-03-20
Customer:	Heather Melton
Phone:	713-555-0277
Insurance claim:	C-1464
Vehicle:	2010 Ford F-150
VIN:	UEN99Z1A830N03143
License plate:	98UE904

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,377.22
Left quarter panel	1	$1,429.37
Left front fender	1	$985.92
Body labor	32.0 hrs	$2,176.63
Paint and materials		$1,255.92
TOTAL		$7,225.06

Appraiser remarks

The vehicle presented with scrape marks and a dented rear quarter panel on the passenger side, along with a cracked taillight lens and a scuffed rear bumper cover. The damage pattern lines up well with a sideswipe during a lane change, and the locations match the account given at intake. The repair plan calls for panel straightening, replacement of the taillihgt assembly, refinishing of the affected panels, and bumper cover repair. The labor hours requested fit the scope of the work. The invoices reviewed show no duplicated line items. No prior damage to this vehicle is known from the records available.