Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

Repair Estimate

Estimate number:	EST-368863
Estimate date:	2025-06-08
Customer:	Jeremy Willis
Phone:	281-555-8403
Insurance claim:	C-1466
Vehicle:	2016 Ford F-150
VIN:	Y9KNLYRY5JFCE5119
License plate:	3-99601

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$400.24
Front bumper cover	1	$299.31
Left front fender	1	$262.07
Body labor	9.9 hrs	$673.17
Paint and materials		$380.85
TOTAL		$2,015.64

Appraiser remarks

The rear bumper cover is cracked across the center and the left quarter panel shows a crease with paint transfer, which lines up with the reported impact in the lot. The repair plan calls for replacing the bumper cover, straightening and refinishing the quarter panel, and recalibrating the parking sensor. The labor hours requested match what this kind of damage typically takes. The invoices submitted contain no duplicated line items or repeat charges. Nothing in the file or the vehicle's condition suggests earlier damage to these areas, so the repairs appear tied to this event.