White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-241897
Estimate date:	March 28, 2024
Customer:	Carol Smith
Phone:	713-555-5579
Insurance claim:	C-1468
Vehicle:	2020 Chevrolet Malibu
VIN:	RVENZJMH8Y7DZ9086
License plate:	YH 1196

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,836.28
Headlamp assembly	1	$1,339.46
Right front door shell	1	$1,176.40
Body labor	39.9 hrs	$2,713.45
Paint and materials		$1,825.05
TOTAL		$8,890.64

Appraiser remarks

The vehicle shows a side impact to the driver's door, with the rear quarter panel and sill also deformed. The crush pattern and paint transfer line up with the reported collision at the intersection. A few older scratches sit along the lower rear door and may predate this crash, so I have noted them separately and excluded them from the repair scope. The plan calls for door and quarter panel replacement, sill repair, refinishing, and recalibration of the side curtain sensor. The labor hours requested fit the extent of the damage, and the invoices contain no repeated charges. Recommend approval of the estimate as written.