Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-851287
Estimate date:	29 Apr 2023
Customer:	Jeffrey Brown
Phone:	346-555-1031
Insurance claim:	C-1469
Vehicle:	2023 Hyundai Elantra
VIN:	XE14TLX097TMK7380
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$553.80
Front bumper cover	1	$469.19
Headlamp assembly	1	$398.44
Body labor	18.5 hrs	$1,260.54
Paint and materials		$499.80
TOTAL		$3,181.77

Appraiser remarks

Inspection of the right rear quarter panel and rear bumper cover shows scraping, a cracked corner of the bumper cover, and a dented rear door skin consistent with a sideswipe during a lane change. It is not fully clear whether every mark on the lower panels came from this impact, so those areas were checked closely against the photographs. The repair plan calls for replacing the bumper cover, refinishing and blending the door, and repairing the quarter panel. The labor hours submitted fit the work described. The invoices show no repeated charges for the same operation. No earlier damage to the vehicle is known from the file or from the owner's account.