Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-259583
Estimate date:	January 10, 2025
Customer:	Larry Griffith
Phone:	281-555-8167
Insurance claim:	C-1470
Vehicle:	2021 Hyundai Elantra
VIN:	0A5WZ1TT35ZC17748
License plate:	CMG-6842

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$999.55
Left quarter panel	1	$1,080.12
Left front fender	1	$800.74
Body labor	29.7 hrs	$2,022.77
Paint and materials		$1,325.39
TOTAL		$6,228.57

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support is bent, with the hood latch and both headlamp assemblies broken away from their mounts. Damage is confined to the front end and the pattern is consistent with the reported low-speed frontal contact. No earlier damage to the vehicle is known, and no prior repair records were noted during inspection. Labor hours listed on the estimate fit the scope of the work described. Two similar charges submitted on the same day are currently under review and have not been approved. Repair plan: replace the bumper cover, radiator support, hood latch, and both headlamps, then refinish and recheck alignment before release.