Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-323420
Estimate date:	6-6-23
Customer:	Brenda Carter
Phone:	346-555-2084
Insurance claim:	C-1476
Vehicle:	2013 Jeep Cherokee
VIN:	9WHJWBW38HR7V5994
License plate:	684 HMB

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$837.25
Headlamp assembly	1	$615.68
Right front door shell	1	$540.09
Body labor	59.2 hrs	$1,303.07
Paint and materials		$827.61
TOTAL		$4,123.70

Appraiser remarks

The vehicle's front left quarter panel, bumper cover and headlamp assembly show damage consistent with the reported left-turn collision, and the pattern of crush and scuffing lines up with the described impact. No prior damage to this vehicle is known from the file or the owner's history. The repair plan calls for replacing the bumper cover and headlamp, refinishing the fender, and recalibrating the driver assistance sensor. The labor hours submitted are roughly three times what a job of this scope normally requires, and the shop should justify or reduce them before approval. Billing records show no repeated charges.