Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-274862
Estimate date:	4 Mar 2025
Customer:	Melanie Chang
Phone:	346-555-6112
Insurance claim:	C-1477
Vehicle:	2016 Jeep Cherokee
VIN:	2UCDXWGV2AR8E2673
License plate:	936-KVX

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,383.10
Left front fender	1	$1,026.53
Front bumper cover	1	$1,113.72
Body labor	48.8 hrs	$2,342.10
Paint and materials		$1,327.10
TOTAL		$7,192.55

Appraiser remarks

Rear bumper cover cracked across the left corner, with the left taillight assembly broken and the trunk lid edge scuffed. The damage pattern is mostly consistent with the low-speed impact described. Repair plan calls for replacing the bumper coevr and taillight, refinishing the trunk lid, and checking the rear sensor bracket. The labor hours look a little high for this scope of work, so I recommend a line-by-line review before approval. No earlier damage to this vehicle is known from the records provided, and the invoices show no repeated charges.