Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-982337
Estimate date:	2023-09-30
Customer:	William Kaiser
Phone:	832-555-7090
Insurance claim:	C-1479
Vehicle:	2021 Nissan Altima
VIN:	A5X55CTE3EF865431
License plate:	VP 0645

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,655.97
Rear bumper cover	1	$1,207.24
Rear body panel	1	$1,096.17
Body labor	56.9 hrs	$2,728.97
Paint and materials		$1,178.93
TOTAL		$7,867.28

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp housing is broken, with the trunk lid showing a crease along its lower edge. The damage pattern lines up with the reported impact, and the farme rails show no sign of sway. A few oledr scratches on the lower quarter panel may predate this loss and have been noted separately. The repair plan calls for replacing the bumper cover and tail lamp assembly, straightening the trunk lid, and refinishing the affected panels. The billing reviewed so far shows no repeated charges. Labor hours appear slightly high for this scope of work and should be checked against standard repair times before approval.