Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-719308
Estimate date:	02/09/2025
Customer:	Bryan Lang
Phone:	713-555-6512
Insurance claim:	C-1481
Vehicle:	2015 Toyota Camry
VIN:	6ND5N11P9KLJB8353
License plate:	4MC1784

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$1,473.01
Rear body panel	1	$952.70
Right tail lamp assembly	1	$884.21
Body labor	31.8 hrs	$2,164.59
Paint and materials		$922.83
TOTAL		$6,397.34

Appraiser remarks

The rear bumper cover is cracked and displaced on the driver's side, with the trunk lid edge deformed and the left tail lamp assembly broken. The crush pattern and paint transfer line up with the impact described in the claim, and the damage sits where a rear-end strike would be expected. No prior damage to this vehicle is known, and the parts and labor on the submitted invoices appear once each with no repeated charges. The labor hours requested fit the scope of work: replace the bumper cover, straighten the trunk lid, replace the lamp assembly, and refinish the affected panels. The repair plan is approved as written.