Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-749765
Estimate date:	January 19, 2024
Customer:	Omar Clark
Phone:	713-555-4936
Insurance claim:	C-1482
Vehicle:	2010 Ford F-150
VIN:	RN9733WE5CBNW5901
License plate:	Y14 8JJ

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$982.90
Trunk lid	1	$643.63
Rear bumper reinforcement	1	$662.63
Body labor	24.4 hrs	$1,662.25
Paint and materials		$1,027.94
TOTAL		$4,979.35

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp housing broken and the trunk lid edge pushed inward, all consistent with the rear-end impact as described. Reinforcement bar and rear quarter panel inspected; no sign of older repairs or prior damage on the vehicle, and nothing in the file suggests earlier loss. Proposed plan: replace bumper cover, tail lamp assembly and reinforcement bar, repair and refinish the trunk lid edge, and recalibrate the parking sensors. Labor hours are in line with the damage shown. The invoices submitted reflect a single set of charges with no duplicated line items. Recommend approval of the repair plan as written.