Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-626330
Estimate date:	28 Sep 2024
Customer:	Eric Garcia
Phone:	713-555-6296
Insurance claim:	C-1485
Vehicle:	2019 Toyota Camry
VIN:	DJMRB5NNX08S75274
License plate:	594 YP1

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$647.75
Front bumper cover	1	$745.07
Left quarter panel	1	$548.62
Right front door shell	1	$647.75
Body labor	58.8 hrs	$1,293.93
Paint and materials		$713.90
TOTAL		$4,597.02

Appraiser remarks

The rear bumper cover is cracked across the center with the left tail lamp housing broken and the trunk lid edge deformed, which lines up with the impact described. Some of the underlying scratches alnog the lower panel look older than this loss and should be noted separately from the new damage. The labor hours written on this estimate run roughly three times what a repair of this scope normally needs, so the figure should be reviewed line by line before approval. Repair plan: replace the bumper cover, tail lamp assembly, and trunk lid skin, then refinish and blend adjacent panels. One duplicate service entry also appears on this estimate and sohuld be removed before the file moves forward.