Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-280892
Estimate date:	April 6, 2023
Customer:	Gary Todd
Phone:	281-555-0748
Insurance claim:	C-1486
Vehicle:	2023 Toyota Camry
VIN:	VULKWZ7LXWYP85939
License plate:	807 EKW

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,272.35
Left front fender	1	$1,105.21
Headlamp assembly	1	$1,304.17
Body labor	45.2 hrs	$3,071.21
Paint and materials		$1,228.70
TOTAL		$7,981.64

Appraiser remarks

Vehicle inspected on arrival following a left-turn collision. The front bumper cover is cracked across the center, the left headlamp assembly is broken, and the hood shows a crease near the leading edge. Damage to the left fender and grille is consistent with the impact described by the insured. No prior damage to this vehicle is known from our records or the owner's account. The repair plan calls for replacing the bumper cover and headlamp, straightening and refinishing the hood, and a radiator support check. Labor hours submitted fit the scope of this work, and the parts and charges on the invoices show no repeated entries. Reocmmend approval of the repair as itemized.