Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-168103
Estimate date:	10-26-23
Customer:	Zachary Huerta
Phone:	832-555-5798
Insurance claim:	C-1487
Vehicle:	2023 Chevrolet Malibu
VIN:	DE7FCR3N3C65P7207
License plate:	676Y2

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$711.72
Headlamp assembly	1	$672.15
Right front door shell	1	$574.07
Body labor	19.4 hrs	$1,316.67
Paint and materials		$647.33
TOTAL		$3,921.94

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support has been pushed rearward, with the hood latch assembly bent and both headlamp brackets broken. Most of this damage lines up with the frontal impact as described. Structural measurements taken at the shop match the repair plan, which calls for replacing the bumper cover, radiator support, hood latch, and both headlamp assemblies, followed by a wheel alignment and a check of the cooling system. The labor hours allotted for each step fit the extent of the damage. The invoices submitted show no repeated charges for the same work. No earlier damage to this vehicle is known from the records reviewed.