Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-600468
Estimate date:	31 Jul 2023
Customer:	Donna Morris
Phone:	713-555-2000
Insurance claim:	C-1488
Vehicle:	2015 Jeep Cherokee
VIN:	JDXMBJ5D017BP2818
License plate:	735-IVIK

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,671.92
Headlamp assembly	1	$1,142.27
Front bumper cover	1	$1,501.45
Body labor	46.5 hrs	$3,163.04
Paint and materials		$1,261.72
TOTAL		$8,740.40

Appraiser remarks

Vehicle inspected at the shop following a collision during a left turn. The front bumper cover is cracked across the center, the left headlamp assembly is broken, and the hood shows a crease with paint loss along the leading edge. The left fender has a dented radiator support area that will need partial replacement and alignment. Damage pattern is largely consistent with the reported impact direction. No prior damage to this vehicle is known to us. The repair plan covers replacing the bumper cover and headlamp, straightening the hood, and refinishing affected panels. Labor hours submitted fit the scope of the damage, and the invoices show no repeated charges for the same work.