Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-184561
Estimate date:	2023-04-13
Customer:	Brandon Allen
Phone:	832-555-8123
Insurance claim:	C-1490
Vehicle:	2018 Ford F-150
VIN:	DPBX12M97BXBL5136
License plate:	DQ1 F4D

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,500.70
Left quarter panel	1	$1,846.28
Right front door shell	1	$1,316.91
Body labor	41.7 hrs	$2,834.31
Paint and materials		$1,520.78
TOTAL		$9,018.98

Appraiser remarks

The front bumper cover is cracked and displaced, with the upper radiator support bent and the hood latch assembly broken loose. The headlamp assemblies show celan breaks at their mounting points, and the grille is torn from its clips. Damage pattern is consistent with the frontal low-speed impact described by the insured. Repair plan calls for replacing the bumper cover, radiator support, hood latch and both headlamp units, followed by a wheel alignment check and a scan for sensor faults. Labor hours line up with the scope of replacement. The shop's invoice history for this vehicle shows no repeated charges, and no prior damage to the vehicle is known to us.