Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-259072
Estimate date:	4-13-25
Customer:	Christian Frederick
Phone:	713-555-9804
Insurance claim:	C-1491
Vehicle:	2019 Jeep Cherokee
VIN:	V0Z29YW55RG4Y4004
License plate:	618 DPH

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$411.56
Right front door shell	1	$419.73
Front bumper cover	1	$321.03
Body labor	12.8 hrs	$871.92
Paint and materials		$351.32
TOTAL		$2,375.56

Appraiser remarks

Inspection of the rear bumper cover, left quarter panel and tail lamp assembly shows damage that is largely consistent with the reported low-speed contact in the parking lot. The repair plan calls for replacing the bumper cover and tail lamp, straightening the quarter panel and refinishing the affected areas. The labor hours requested match the scope of the work shown in the photographs. The invoices on file list each operation once with no duplicated charges. Nothing in the vehicle's history or the inspection suggests earlier damage to these components, so the proposed repairs appear to address only this incident.