Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-206778
Estimate date:	03/06/2023
Customer:	Thomas Jackson
Phone:	832-555-6799
Insurance claim:	C-1493
Vehicle:	2017 Chevrolet Malibu
VIN:	GREF9XSS8ZH781639
License plate:	YYE 512

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,150.03
Left quarter panel	1	$735.14
Front bumper cover	1	$735.39
Headlamp assembly	1	$1,150.03
Body labor	73.2 hrs	$1,611.04
Paint and materials		$870.21
TOTAL		$6,251.84

Appraiser remarks

The front bumper cover is cracked across the center, the grille bracket is bent, and the hood latch and both headlamp assemblies show impact marks consistent with a frontal stirke at low speed. The radiator support has a slight shift that fits the same force path. Nothing on the vehicle points to older or unrelated damage. The proposed plan replaces the bumper cover, grille bracket, and affected lamp assemblies, then realigns the hood and checks the cooling system. The labor hours submitted run roughly three times what this scope normally requires, so the shop should itemize each task. A duplicate entry for one service also appears on the invoice, which the provider has acknowledged as a repeat. Those lines need correction before payment review.