White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-710469
Estimate date:	July 23, 2024
Customer:	Carl Herrera
Phone:	713-555-1127
Insurance claim:	C-1494
Vehicle:	2022 Nissan Altima
VIN:	FV7J58PW1EG3P3606
License plate:	572-GBB

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,554.25
Left quarter panel	1	$1,327.15
Front bumper cover	1	$1,556.15
Body labor	40.1 hrs	$2,727.31
Paint and materials		$1,964.27
TOTAL		$9,129.13

Appraiser remarks

Inspection of the rear bumper cover, left quarter panel and tail lamp assembly shows damage consistent with the reported low-speed contact in a parking lot, and the pattern of deformation lines up with the impact described. No prior damage to the vehicle is known from the file or from the inspection. The proposed repair plan is to replace the bumper cover, refinish the quarter panel and install a new tail lamp, and the labor hours listed fit the work required. Two similar charges entered on the same day are currenlty under review and will be confirmed before payment is released.