Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-599473
Estimate date:	01/20/2024
Customer:	Edward Rogers
Phone:	281-555-1067
Insurance claim:	C-1495
Vehicle:	2020 Jeep Cherokee
VIN:	6NN5EW4D9W2YZ5979
License plate:	DOQ 679

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$590.60
Front bumper cover	1	$330.00
Left quarter panel	1	$344.67
Body labor	12.7 hrs	$865.76
Paint and materials		$383.00
TOTAL		$2,514.03

Appraiser remarks

The vehicle presented with scraping and paint transfer along the right rear quarter panel, a cracked rear bumper cover at the right corner, and a bent right side mirror housing. The damage pattern runs along one side of the car and lines up well with a sideswipe during a lane change. No prior damage to this vehicle is known, and the repair plan calls for replacing the bumper cover, refinishing the quarter panel, and swapping the mirror assembly. The labor hours requested match what this damage typically requires, and the invoiced items show no duplicated charges. The plan is reasonable and can proceed as written.