# Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-724779 |
| **Estimate date:** | 2025-04-19 |
| **Customer:** | Matthew Reed |
| **Phone:** | |
| **Insurance claim:** | C-1497 |
| **Vehicle:** | 2016 Chevrolet Malibu |
| **VIN:** | BG1F4A9Z9HKPR3436 |
| **License plate:** | A 906695 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Headlamp assembly | 1 | $1,602.29 |
| Left front fender | 1 | $1,402.45 |
| Left quarter panel | 1 | $954.83 |
| Body labor | 38.3 hrs | $2,601.76 |
| Paint and materials | | $1,729.82 |
| TOTAL | | $8,291.15 |

### Appraiser remarks

Inspection of the rear quarter panel and rear bumper cover shows scraping, paint transfer and a cracked corner bracket on the driver's side, consistent with a sideswipe during a lane change. The damage pattern lines up with the impact as described. The proposed repair plan calls for replacing the bumper cover, refinishing the quarter panel, and straightening the bracket mount. The labor hours requested fit the scope of this damage. The shop's invoices show no duplicated or repeated charges. No prior damage to this vehicle is known from the file or the owner's records.