Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-639647
Estimate date:	September 24, 2023
Customer:	Allen Yang
Phone:	832-555-4918
Insurance claim:	C-1498
Vehicle:	2018 Ford F-150
VIN:	9C6L9S3P65LWL7948
License plate:	A54 4BC

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$1,738.85
Trunk lid	1	$1,286.98
Rear bumper cover	1	$1,099.33
Body labor	35.5 hrs	$2,414.15
Paint and materials		$1,656.84
TOTAL		$8,196.15

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease along its lower edge, with the tail lamp assembly broken on the driver side. The damage lines up with the impact as it was described, and no older damage to this vehicle is on record. The repair plan calls for replacing the bumper cover and tail lamp, straightening the trunk lid, and refinishing the rear panel to match. The labor hours listed are in line with work of this kind. The invoices submitted show no repeated charges for the same items.