# Romero Auto Body

893 Nathaniel Estates Apt. 957
Houston, TX
Phone 713-555-5430

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-303030 |
| **Estimate date:** | 27 Aug 2023 |
| **Customer:** | Annette Taylor |
| **Phone:** | 346-555-8011 |
| **Insurance claim:** | C-1499 |
| **Vehicle:** | 2012 Jeep Cherokee |
| **VIN:** | EAB0BF9S7J0SD0175 |
| **License plate:** | |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Right front door shell | 1 | $556.49 |
| Headlamp assembly | 1 | $489.32 |
| Hood panel | 1 | $419.63 |
| Body labor | 19.9 hrs | $955.21 |
| Paint and materials | | $480.51 |
| TOTAL | | $2,901.16 |

### Appraiser remarks

The front bumper cover is cracked across the center and the driver-side headlamp assembly is broken. The radiator support shows bending consistent with a frontal load, and the hood latch area has a shallow crease. Most of this damage lines up well with the impact as described. The repair plan calls for replacing the bumper cover, headlamp assembly, and hood, with a frame check and refinishing of the affected panels. Labor hours are slightly above what this damage typically needs, so the shop should justify the extra time. The billing records show no repeated charges, and there is no known prior damage to this vehicle.