Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-672152
Estimate date:	2024-07-08
Customer:	Lisa Mack
Phone:	713-555-6090
Insurance claim:	C-1500
Vehicle:	2022 Toyota Camry
VIN:	E4C0NEPL9CVB15995
License plate:	YWK6006

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,472.40
Hood panel	1	$1,129.14
Headlamp assembly	1	$1,179.98
Body labor	45.8 hrs	$2,197.52
Paint and materials		$1,547.02
TOTAL		$7,526.06

Appraiser remarks

The vehicle sohws front-end damage consistent with a low-speed head-on impact, including a cracked bumper cover, a bent radiator support, and a damaged hood and headlamp assembly. The proposed repair plan calls for replacing the bumper cover and hood, straightening the support, and refinishing the affected panels. Some of the damage may not be fully explained by this collision, and a few old scratches near the lower quarter panel may predate the loss. The shop's itemized bills show no repeated charges. The labor hours appear somewhat high for the scope of damage described, so a line-by-line review is recommended before approval.