LakeBreeze - Equipment Not Working Data		
Category	Fire Alarm System	Fire Extinguishers
S.No	10	12
Description of Issue	F-Block Fire alarm system not working	Total 37 fire extinguishers were discharged.
Root Cause	Due to PCB board failure	Automatically got discharged.
Action Required/ Planned	Need to replace with new alarm panel	Need to refill
Pending from days	28	30
Estimated Date of Completion	30.09.2019	30.09.2019
Responsibility	Society	Society
Notified to the concerned	Society	Society