Lotus STP Not working Data	
Category	Hydro Pneumatic Pump
S.No	4
Description of Issue	Hydro pneumatic pump not working
Root Cause	Frequent priming loss
Action Required / Planned	Vendor suggested to install a support arrangement for suction line to avoid vibrations. Awaiting for support from MEP department
Pending from days	15
Responsibility	APMS
Notified to the concerned	MEP & purchase department