Elina - Equipment Not Working Data	
Category	Booster Pumps
S.No	4
Description of Issue	Booster pumps kept in manual mode
Root Cause	NRV ring washer problem
Action Required/ Planned	Manual indent raised (Indent no: 7988,7989, Date: 13.10.2018)
Pending from days	55
Responsibility	APMS / ACEPL
Notified to the concerned	APMS / ACEPL