## Borewells not working status as on 31-8-2019

S.No	Community	Borewells		Reasons for Failure								
		Total	No. of Bores: Not working	No Ground Water	Over Load	Motor burnt	Cable Problem	Pump / Motor wear & tear	Others	Dry Run Protection	Flow Meter	Remarks
1	Aura	3	01	-	-	-		-	-	Available	Available	-
2	Boulevard	5	3	2	-	-	-	1	-	NA	NA	-
3	Cyber Life	4	0	-	-	-	-	-	-	Available	Available	-
4	Elina	4	0	-	-	-	-	-	-	Available	Available	-
5	Elixir	6	6	6	-	-	-	-	•	Available	Available	-
6	Gardenia	5	1	-	-	-	-	-	1	NA	NA	Condemned
7	Kanopy Tulip	4	0	-	-	-	-	-	-	NA	NA	-
8	LakeBreeze	3	1	1	-	-	-	-	•	NA	NA	-
9	Lotus	2	00	-	-	-	-	-	-	NA	NA	-
10	Oosman's Everest	2	0	-	-	-	-	-	-	Available	Available	-
11	Sarovar	13	10	3	3	4	-	-	-	Available	Available	-
12	Sarovar Grande	6	0	-	-	-	-	-	-	Available	Available	-
13	Westside	5	5	5	-	-	-	-	-	Available	Available	-