Borewells not working status as on 31-3-2019

S.No	Community	Borewells		Reasons for Failure								
		Total	No. of Bores: Not working	No Ground Water	Over Load	Motor burnt	Cable Problem	Pump / Motor wear & tear	Others	Dry Run Protection	Flow Meter	Remarks
1	Sarovar	13	9	3	2	4	-	-	-	Available	Available	-
2	Sarovar Grande	6	0	-	-	-	-	-	-	Available	Available	-
3	Aura	3	0	-	-	-	-	-	-	Available	Available	-
4	Boulevard	5	3	2	-	-	-	1	-	NA	NA	-
5	LakeBreeze	3	1	1	-	-	-	-	-	NA	NA	-
6	Gardenia	5	1	-	-	-	-	-	1	NA	NA	Borewell abended
7	Kanopy Tulip	4	0	-	-	-	-	-	-	Available	Available	-
8	Lotus	2	0	-	-	-	-	-	-	NA	NA	-
9	Oosman's Everest	2	0	-	-	-	-	-	-	NA	Available	-
10	Elina	4	0	-	-	-	-	-	-	NA	Available	-
11	Cyber Life	4	0	-	-	-	-	-	-	NA	Available	-
12	Elixir	6	3	3	-	-	-	-	-	Available	Available	-