

ACME Mine

Safety, Health and Management System

Comprehensive Document Set



MINE GUARD AI

Mine Guard AI SHMS Documentation

Establishing Safety Standards and Procedures for Mining Operations

CONFIDENTIAL | FOR AUTHORIZED PERSONNEL ONLY

793F Dumping Operation

SAFE WORK INSTRUCTION

Document Title: 793F Dumping Operation Document Type: Safe Work Instruction SHMS Group: Surface Operations Effective Date: 21/06/2025 Review Period: 3 years

1. TASK OVERVIEW

This instruction outlines the safe and correct method for operating a Caterpillar 793F haul truck during dumping operations at ACME Mine. The objective is to ensure operator safety, equipment integrity, and compliance with the Queensland Coal Mining Safety and Health Act 1999 and Regulation 2017.

2. REQUIRED PPE

Personnel involved in this task must wear the following PPE at all times:

- Safety helmet (hard hat)
- High visibility clothing (long sleeves and trousers)
- Steel-capped safety boots
- Safety glasses (clear or tinted as appropriate)
- Hearing protection (ear plugs or earmuffs)
- Gloves (as required for inspections or maintenance tasks)

3. PREREQUISITE TRAINING

Personnel must have successfully completed the following training and hold current competencies:

- RIIMPO338 – Conduct rigid haul truck operations (Caterpillar 793F)
- Mine site induction and familiarisation training
- Site-specific dumping procedures and hazard awareness training
- Emergency response and evacuation training

4. HAZARDS AND CONTROLS

Vehicle rollover or instability during dumping

Control: Maintain level ground at dump edge, ensure adequate berm height, approach dump edge squarely, and dump load evenly and slowly.

Interaction with other mobile equipment or personnel

Alcohol and Drug Testing Procedure

Human Factors SHMS Group Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear guidelines for alcohol and drug testing at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017. This procedure aims to maintain a safe and healthy working environment by preventing impairment-related incidents and promoting fitness for duty among all personnel.

2. Scope

This procedure applies to all employees, contractors, visitors, and any other personnel entering or performing work at ACME Mine. It covers all forms of alcohol and drug testing, including pre-employment, random, post-incident, reasonable suspicion, and return-to-work testing.

3. Definitions

Alcohol

Any beverage or substance containing ethanol.

Drug

Any substance, legal or illegal, prescription or non-prescription, that impairs or has the potential to impair an individual's ability to safely perform their duties.

Fit for Duty

A state in which an individual is physically, mentally, and emotionally capable of safely performing assigned tasks without impairment.

Random Testing

Unannounced testing conducted on randomly selected personnel.

Reasonable Suspicion Testing

Testing conducted when observable signs or behaviours indicate possible impairment.

Post-Incident Testing

Testing conducted after an incident or accident to determine if impairment was a contributing factor.

4. Roles & Responsibilities

Bomb Threat and Security Policy

Emergency Management Effective Date: 21/06/2025 Review Period: 3 years

1. Overview

ACME Mine is committed to ensuring the safety and security of all personnel, contractors, visitors, and assets. This policy outlines the procedures and responsibilities for managing bomb threats and security incidents, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and the Coal Mining Safety and Health Regulation 2017. The policy aims to minimise risk, protect life and property, and ensure a rapid, coordinated response to any bomb threat or security incident.

2. Key Points

2.1 Bomb Threat Response

All bomb threats must be treated seriously and immediately reported to the Emergency Response Coordinator (ERC) or Mine Site Senior Executive (SSE). Personnel receiving a bomb threat via telephone should remain calm, gather as much information as possible, and record details such as caller identity, voice characteristics, background noises, and exact wording of the threat. Upon notification, the ERC or SSE will initiate the Emergency Response Plan, notify emergency services, and coordinate evacuation and search procedures as required. All personnel must follow instructions from the ERC, SSE, or emergency services promptly and without question. The ERC and SSE will maintain clear communication with emergency services and ensure the site is secured and controlled until the threat is resolved.

2.2 Security Management

Access to ACME Mine is strictly controlled through designated entry points. All personnel, contractors, and visitors must display authorised identification at all times. Security personnel will conduct regular patrols and inspections of critical infrastructure, buildings, and operational areas to detect and deter unauthorised access or suspicious activities. Personnel must report any suspicious activity, unauthorised persons, or security breaches immediately to their supervisor, security personnel, or the ERC. Security incidents will be documented, investigated, and reported in accordance with the site's incident reporting procedures and regulatory requirements. ACME Mine will conduct regular training and drills to ensure personnel are familiar with bomb threat and security response procedures.

3. Review

This policy will be reviewed every three years or following any significant incident, legislative change, or operational modification to ensure continued effectiveness and compliance with relevant legislation and industry best practice. The SSE is responsible for ensuring the review is conducted and documented appropriately.

Charging and Stemming Checklist

Frequency of Use: To be completed prior to each blasting operation.

Inspection Items:

1. Personnel involved in charging and stemming operations have current competencies and authorisations.	☐ Yes ☐ No
2. Appropriate Personal Protective Equipment (PPE) is worn by all personnel involved in charging and stemming activities.	☐ Yes ☐ No
3. Explosives and initiating systems are transported, handled, and stored in compliance with site procedures and relevant legislation.	☐ Yes ☐ No
4. Blast holes are inspected and confirmed clear of obstructions, water, or foreign materials prior to charging.	☐ Yes ☐ No
5. Correct explosive products and quantities are loaded into blast holes as per approved blast design.	☐ Yes ☐ No
6. Charging equipment is inspected, maintained, and operated according to manufacturer's specifications and site procedures.	☐ Yes ☐ No
7. Stemming material used is appropriate, dry, and free from contaminants, and stemming height complies with the approved blast design.	☐ Yes ☐ No
8. Blast hole collars are clearly marked and protected to prevent accidental damage or premature initiation.	☐ Yes ☐ No
9. Exclusion zones and signage are established and clearly communicated to all relevant personnel prior to commencing charging and stemming operations.	☐ Yes ☐ No

Critical Monitoring Radar Operations

ACME Mine Safe Work Instruction

SHMS Group: Geotechnical Hazards Effective Date: 21/06/2025 Review Period: 3 years

1. Task Overview

This instruction outlines the safe operation, maintenance, and monitoring of critical slope stability radar systems used at ACME Mine. The radar system provides real-time monitoring and early detection of slope instability, ensuring personnel safety and operational continuity in active mining areas.

2. Required PPE



Head Protection

Safety helmet with chin strap



Visibility

High-visibility clothing (long sleeve shirt and trousers with reflective strips)



Eye Protection

Safety glasses with side protection



Foot Protection

Steel-capped safety boots



Hand Protection

Gloves suitable for electrical and mechanical tasks



Hearing Protection

Ear plugs or ear muffs when working near radar equipment generators or other noisy equipment

3. Prerequisite Training

Personnel operating or maintaining radar monitoring systems must complete the following training:

- ACME Mine Site Induction
- Geotechnical Hazard Awareness Training
- Radar System Manufacturer's Operational Training
- Working at Heights Training (if required for radar installation or maintenance)
- Electrical Safety Awareness Training (for electrical maintenance tasks)

4. Hazards and Controls

Critical Monitoring Radar Procedure

Geotechnical Hazards Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to outline the requirements for the effective deployment, operation, maintenance, and monitoring of critical slope stability radar systems at ACME Mine. This ensures early detection, timely response, and effective management of slope instability hazards, thereby protecting personnel, equipment, and operational continuity in compliance with the Queensland Coal Mining Safety and Health Act 1999 and Regulation 2017.

2. Scope

This procedure applies to all personnel involved in the installation, operation, maintenance, monitoring, and response actions associated with critical monitoring radar systems used for slope stability management at ACME Mine.

3. Definitions

Critical Monitoring Radar

Ground-based radar system used for continuous real-time monitoring of slope stability, detecting sub-millimetre movements and providing early warning of potential slope failures.

Trigger Action Response Plan (TARP)

Documented plan outlining specific actions and responses required when radar monitoring thresholds are exceeded.

Geotechnical Engineer

Qualified professional responsible for geotechnical hazard assessment and management at the mine.

Slope Stability Monitoring Technician

Competent person trained and authorised to operate, maintain, and monitor radar systems and associated software.

Exclusion Zone

Clearly demarcated area established to restrict access when slope instability hazards are identified.

4. Roles & Responsibilities

Site Senior Executive (SSE)

Open Cut Examiner (OCE)

D11 Dozer Push Operations

SAFE WORK INSTRUCTION

Document Title: D11 Dozer Push Operations Document Type: Safe Work Instruction SHMS Group: Surface Operations Effective Date: 21/06/2025 Review Period: 3 years

1. TASK OVERVIEW

This Safe Work Instruction outlines the safe procedures for conducting push operations using Caterpillar D11 Dozers at ACME Mine. Push operations involve using D11 Dozers to move overburden, spoil, or coal material to designated dump or stockpile locations. This task is critical for maintaining effective bench management, spoil placement, and operational efficiency.

2. REQUIRED PPE



Head Protection

High-visibility safety helmet with reflective tape



Visibility

High-visibility clothing (long sleeve shirt and trousers)



Foot Protection

Steel-capped safety boots



Eye Protection

Safety glasses (clear or tinted as appropriate)



Hearing Protection

Hearing protection (ear plugs or earmuffs)



Hand Protection

Gloves (as required for inspections and maintenance tasks)



Respiratory Protection

Dust mask or respirator as required by risk assessment

Daily Supervisor Inspection Checklist

Frequency of Use: Daily, prior to commencement of shift activities.

Inspection Items:

1 Mobile Equipment and Vehicles

- Pre-start inspections completed and documented.
- Equipment free from visible damage or defects.
- Seat belts, lights, horns, reversing alarms, and emergency stops operational.
- Tyres and wheels in good condition with no visible damage or excessive wear.

2 Haul Roads and Access Ways

- Roads clear of obstructions, debris, and excessive spillage.
- Adequate signage and delineation in place and clearly visible.
- Road surface condition suitable for safe vehicle operation.
- Berms and windrows properly constructed and maintained.

3 Excavation and Dump Areas

- Highwall and low wall conditions inspected for signs of instability or hazards.
- Dump areas stable, clearly delineated, and free from visible cracks or slumping.
- Adequate lighting provided for night shift operations.
- Barricades and signage in place to restrict unauthorised access.

4 Work Areas and Infrastructure

- Walkways, stairways, and access points clear, unobstructed, and in good condition.
- Handrails, guardrails, and barriers securely installed and maintained.
- Lighting adequate for safe working conditions.
- Housekeeping standards maintained, with no accumulation of waste or materials.

5 Environmental Controls

- Dust suppression measures operational and effective.
- Spill kits available and fully stocked at designated locations.
- Waste bins provided and regularly emptied.
- No visible leaks or spills from equipment or storage areas.

6 Emergency Preparedness

Drill and Blast Procedure

ACME Mine Safety and Health Management System (SHMS) Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear guidelines for safe and efficient drilling and blasting operations at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017. This procedure aims to minimise risks associated with drill and blast activities, including explosives handling, drilling operations, blast initiation, and post-blast management.

2. Scope

This procedure applies to all personnel involved in drill and blast operations at ACME Mine, including employees, contractors, supervisors, and visitors present within designated blasting areas.

3. Definitions

Authorised Person

A competent person appointed by ACME Mine management to undertake specific drill and blast activities.

Blast Exclusion Zone

Clearly defined area around blasting operations from which personnel and equipment must be evacuated prior to blasting.

Blast Controller

A competent person appointed to coordinate and control blasting activities.

Misfire

An occurrence when explosives fail to detonate as planned.

Explosives Magazine

A secure facility approved for the storage of explosives.

Stemming

Material placed in blast holes to confine explosives and direct blast energy effectively.

4. Roles & Responsibilities

Site Senior Executive (SSE)

Shotfirer

Emergency Contact Poster Template

When to Use

This Emergency Contact Poster Template shall be used to clearly display critical emergency contact information throughout ACME Mine operational areas, offices, workshops, crib rooms, and other prominent locations. It ensures personnel have immediate access to essential emergency contacts during incidents or emergencies, facilitating rapid response and effective communication in line with the ACME Mine Emergency Management Plan and Queensland CSMH legislation.

Instructions for Use

1. Populate the poster with accurate and current emergency contact information relevant to the specific location or operational area.
2. Ensure contact details include internal emergency numbers, external emergency services, and key site personnel responsible for emergency management.
3. Clearly display the completed poster in prominent, accessible locations, ensuring visibility and readability at all times.
4. Regularly review and update the poster to reflect any changes in personnel, contact numbers, or emergency procedures.
5. Replace damaged or illegible posters immediately to maintain effectiveness.

Example Entries

Internal Emergency Contacts

- Emergency Response Team (ERT)
Coordinator: 07 4123 4567 or UHF Channel 12
- Control Room
Supervisor: 07 4123 4568 or UHF Channel 10
- First Aid Station: 07 4123 4569 or UHF Channel 9

External Emergency Contacts

- Ambulance / Fire / Police: 000
- Queensland Mines Inspectorate (Emergency Reporting): 07 3237 1696
- Local Hospital (Emerald Hospital): 07 4987 9400
- Poisons Information Centre: 13 11 26

Key Site Personnel

- SSE (Site Senior Executive): John Smith, 0400 123 456
- HSE Manager: Jane Doe, 0400 234 567
- Emergency Response Coordinator: Mark Johnson, 0400 345 678

Approval

Emergency Response Plan

ACME Mine

1. Objective

The objective of this Emergency Response Plan is to establish clear, structured, and effective procedures to manage emergencies at ACME Mine, ensuring the safety and health of all personnel, contractors, visitors, and the surrounding community. This plan aims to minimise harm, mitigate damage, and facilitate rapid recovery from emergency situations, in compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Background

ACME Mine is an open-cut coal operation located in Queensland, involving significant mobile plant operations, blasting activities, coal handling and processing facilities, and associated infrastructure. Potential emergency scenarios identified include fires, explosions, vehicle collisions, slope failures, hazardous materials spills, medical emergencies, severe weather events, and environmental incidents. This plan outlines the structured approach to emergency preparedness, response, and recovery, ensuring compliance with legislative requirements and industry best practice.

3. Key Actions



Communication Systems

Establish and maintain clear communication channels and emergency notification systems, including radios, alarms, and site-wide PA systems.



Emergency Drills

Conduct regular risk assessments and scenario-based emergency drills to test and evaluate the effectiveness of emergency response procedures.



Evacuation Routes

Clearly identify and maintain emergency evacuation routes, muster points, and refuge areas, ensuring they are accessible, clearly marked, and regularly inspected.



Training

Provide appropriate emergency response training to all personnel, including induction training, refresher training, and specialised training for Emergency Response Team (ERT) members.

Explosives Transport and Handling Plan

ACME Mine Effective Date: 21/06/2025 Review Period: 3 years SHMS Group: Drill and Blast

1. Objective

The objective of this Explosives Transport and Handling Plan is to ensure the safe, secure, and compliant transportation, storage, handling, and use of explosives at ACME Mine. This plan aims to eliminate or minimise risks associated with explosives, protecting personnel, equipment, the environment, and maintaining compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Background

ACME Mine conducts regular blasting operations as part of its open-cut coal mining activities. Explosives are essential for efficient and effective fragmentation of overburden and coal seams. Due to the inherent risks associated with explosives, including accidental detonation, theft, environmental contamination, and personal injury, stringent controls and procedures must be implemented and maintained. This plan outlines the necessary measures to manage these risks effectively.

3. Key Actions

Regulatory Compliance

All explosives transport activities must comply with the Australian Explosives Code (AEC) and relevant Queensland legislation.

Personnel Authorisation

Only authorised, trained, and competent personnel shall handle, transport, and use explosives.

Transport Requirements

Explosives shall be transported in approved, clearly marked, and fit-for-purpose vehicles equipped with appropriate fire extinguishers, signage, and emergency response equipment.

Transport Routes

Vehicles transporting explosives must follow designated routes, avoiding congested or populated areas where possible.

Fatigue Management Policy

1. Overview

ACME Mine recognises fatigue as a significant safety and health risk that can adversely affect the wellbeing of our workforce and the safe operation of our mine. Fatigue can impair judgement, reduce concentration, slow reaction times, and increase the likelihood of incidents and injuries. In line with our obligations under the Queensland Coal Mining Safety and Health Act 1999 and the Coal Mining Safety and Health Regulation 2017, ACME Mine is committed to proactively managing fatigue risks through effective controls, awareness, and continuous improvement.

2. Key Points

ACME Mine will implement and maintain a fatigue management system that includes:

Working Hours

Clearly defined working hour limits and roster arrangements designed to minimise fatigue risk, including adequate rest periods between shifts and appropriate shift rotation.

Monitoring

Monitoring and review of fatigue management practices through regular audits, incident investigations, and feedback from workers and supervisors to ensure continuous improvement.

Facilities

Provision of adequate facilities and resources, such as rest areas, hydration stations, and comfortable accommodation, to support personnel in managing

Risk Assessment


Regular fatigue risk assessments to identify, evaluate, and control fatigue-related hazards within operational activities, particularly in high-risk tasks such as haul truck operations, dragline operations, and maintenance activities.

Training

Training and education programs for all employees and contractors to raise awareness of fatigue risks, signs of fatigue, and individual responsibilities for fatigue management.

Reporting

Processes for employees and contractors to report fatigue-related concerns or incidents without fear of reprisal, ensuring open communication and prompt



Fire and Explosion Response Procedure

ACME Mine Safety and Health Management System (SHMS) Emergency Management Group

Effective Date: 21/06/2025 Review Period: 3 Years

1. Purpose

The purpose of this procedure is to establish clear guidelines for responding to fire and explosion incidents at ACME Mine, ensuring the safety of all personnel, minimising damage to property and equipment, and maintaining compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Scope

This procedure applies to all ACME Mine personnel, contractors, visitors, and other stakeholders who may be present on site. It covers all operational areas, including workshops, coal handling and processing plant (CHPP), mobile equipment, explosives storage areas, fuel storage and dispensing areas, and administration buildings.

3. Definitions

Fire

An uncontrolled combustion event involving flammable or combustible materials.

Explosion

A sudden and violent release of energy resulting from rapid chemical reaction, pressure build-up, or ignition of explosive atmospheres.

Emergency Response Team (ERT)

A trained group of personnel responsible for responding to site emergencies, including fires and explosions.

Incident Controller

The person responsible for overall management and coordination of emergency response activities during an incident.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources are available

Emergency Response Coordinator

- Maintain emergency response equipment

First Aid Response Procedure

Emergency Management Group Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

This procedure outlines the requirements and processes for providing prompt and effective first aid response to injuries and illnesses occurring at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017. The aim is to minimise injury severity, promote rapid recovery, and maintain the health and safety of all personnel on site.

2. Scope

This procedure applies to all ACME Mine personnel, contractors, visitors, and other persons present on site at any time. It covers first aid preparedness, response to incidents requiring first aid, and ongoing management of first aid facilities and equipment.

3. Definitions

First Aid

Immediate care provided to an injured or ill person until professional medical treatment is available.

First Aid Officer

A person trained and certified in first aid response, appointed by ACME Mine management.

Incident

Any event resulting in injury or illness requiring first aid treatment.

First Aid Facility

Designated area or room equipped for the provision of first aid treatment.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and facilities are provided for first aid response.
- Appoint qualified First Aid Officers and ensure their training remains current.
- Ensure compliance with legislative requirements and this procedure.

First Aid Officers

- Maintain current first aid qualifications and skills.
- Provide immediate first aid treatment to injured or ill persons.
- Maintain first aid kits and facilities, ensuring they are fully stocked, accessible, and ready for use.

Fit for Work Procedure

Human Factors Group Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear guidelines and responsibilities to ensure all personnel at ACME Mine are fit for work, free from impairment due to fatigue, alcohol, drugs, illness, injury, or other factors that may adversely affect their ability to safely perform their duties, in accordance with the Queensland Coal Mining Safety and Health Act 1999 and the Coal Mining Safety and Health Regulation 2017.

2. Scope

This procedure applies to all employees, contractors, visitors, and other personnel entering or working within ACME Mine operational areas or performing duties related to mine operations.

3. Definitions

Fit for Work

A physical, mental, and emotional state enabling an individual to perform assigned tasks competently and safely, without impairment or risk to themselves or others.

Fatigue

A state of physical or mental exhaustion reducing an individual's ability to perform tasks safely and effectively.

Impairment

Reduced ability to perform tasks safely due to fatigue, illness, injury, medication, alcohol, drugs, or other factors.

Drug and Alcohol Testing

The process of conducting tests to detect the presence of alcohol or prohibited substances in an individual's system.

Supervisor

A person authorised by ACME Mine management to oversee and direct the work of others.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure implementation and compliance with this procedure across ACME Mine.
- Provide adequate resources and support

Workers (Employees, Contractors, Visitors)

- Report to work fit for duty, free from impairment.

Geotechnical Operational Checklist

Frequency of Use: Daily, prior to commencement of each shift and following significant weather events or blasting activities.

Inspection Items:

1. Pit walls and benches visually inspected for signs of instability, including cracking, slumping, bulging, or loose material.	☐ Yes ☐ No
2. Highwall and low wall areas checked for evidence of rockfall, erosion, or water seepage.	☐ Yes ☐ No
3. Haul roads and ramps inspected for cracks, subsidence, surface deterioration, or drainage issues.	☐ Yes ☐ No
4. Dumps and stockpiles examined for stability, slope angle compliance, and signs of movement or erosion.	☐ Yes ☐ No
5. Drainage systems assessed for blockages, damage, or inadequate flow that could impact slope stability.	☐ Yes ☐ No
6. Geotechnical monitoring instrumentation (e.g., slope stability radar, inclinometers, piezometers) checked for operational functionality and data anomalies.	☐ Yes ☐ No
7. Protective bunds and barriers inspected for integrity, correct placement, and adequate height.	☐ Yes ☐ No
8. Exclusion zones clearly defined, signposted, and maintained in accordance with geotechnical recommendations.	☐ Yes ☐ No

Action Required if Not Compliant:

- 1 Immediately isolate and barricade the affected area to prevent personnel and equipment access.

Ground Control Management Plan

ACME Mine Effective Date: 21/06/2025 Review Period: 3 Years SHMS Group: Geotechnical Hazards

1. Objective

The objective of this Ground Control Management Plan is to establish and maintain effective management strategies to ensure the stability of pit walls, spoil dumps, haul roads, and other geotechnical structures at ACME Mine. This plan aims to prevent geotechnical incidents, protect the safety and health of all personnel, and comply fully with the Queensland Coal Mining Safety and Health Act 1999 and the Coal Mining Safety and Health Regulation 2017.

2. Background

Ground control hazards at ACME Mine primarily arise from geological conditions, mining methods, and environmental factors. Typical hazards include slope instability, spoil dump failures, rock falls, and subsidence. Effective ground control management is essential to mitigate these hazards, ensuring safe working conditions and operational continuity. Historical geotechnical assessments and ongoing monitoring have identified specific areas of concern, including highwall stability in the northern pit area and spoil dump stability in the southern waste emplacement area.

3. Key Actions

Geotechnical Assessments

Conduct regular geotechnical assessments and inspections by qualified geotechnical engineers, focusing on pit walls, spoil dumps, haul roads, and critical infrastructure.

Geotechnical Modelling

Develop and maintain detailed geotechnical models and slope stability analyses to inform mine planning and operational decisions.

Exclusion Zones

Establish and maintain exclusion zones clearly marked with signage and barriers in areas identified as potentially unstable or hazardous.

Monitoring Program

Implement a comprehensive ground control monitoring program, including the use of slope stability radar, prism monitoring, extensometers, and visual inspections.

Training and Awareness

Heavy Vehicle Interaction Plan

ACME Mine Safety and Health Management System Effective Date: 21/06/2025 Review Period: 3 Years SHMS Group: Mobile Equipment

1. Objective

The objective of this Heavy Vehicle Interaction Plan is to establish clear and effective controls to eliminate or minimise risks associated with interactions between heavy mobile equipment, light vehicles, pedestrians, and fixed infrastructure at ACME Mine. This plan ensures compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017, promoting a safe working environment for all personnel.

2. Background

Heavy vehicle interactions have historically represented significant safety risks within open-cut coal mining operations. Incidents involving heavy mobile equipment, such as haul trucks, excavators, graders, dozers, and water carts, interacting with smaller vehicles, pedestrians, and fixed structures, can result in serious injuries or fatalities. Analysis of industry incidents highlights contributing factors such as limited visibility, inadequate communication, insufficient separation distances, and ineffective traffic management. ACME Mine recognises the critical importance of proactively managing these risks through robust planning, training, and operational controls.

3. Key Actions

Traffic Management

Clearly defined haul roads, intersections, and parking areas shall be established and maintained, including appropriate signage, delineation, and lighting. Traffic flow shall be designed to minimise intersections and vehicle crossovers. Speed limits shall be clearly posted and enforced.

Reporting

Separation

Designated pedestrian walkways and exclusion zones shall be provided and clearly marked. Physical barriers, bund walls, or berms shall be installed where practicable to separate heavy equipment from pedestrians and light vehicles. Personnel shall not enter heavy equipment operating areas without clear communication and authorisation.

Communication

All vehicles operating

High Voltage Access Procedure

Procedure Energy Control Group Effective Date: 21/06/2025 Review Period: 3 Years

1. Purpose

The purpose of this procedure is to establish clear and consistent requirements for safe access to high voltage (HV) installations at ACME Mine. This procedure ensures compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017, protecting personnel from electrical hazards associated with HV equipment and infrastructure.

2. Scope

This procedure applies to all ACME Mine personnel, contractors, and visitors requiring access to high voltage installations, including substations, switchyards, transformers, HV switchgear, and overhead HV lines within the mine lease area.

3. Definitions

High Voltage (HV)

Voltage exceeding 1000 volts AC or 1500 volts DC.

Authorised Person

A competent person trained, assessed, and authorised by ACME Mine management to perform specific HV tasks.

Isolation

The process of disconnecting HV equipment from all sources of electrical energy and securing it against inadvertent reconnection.

Permit to Work (PTW)

A formal written authorisation issued by an authorised person, allowing specific work to be undertaken safely on HV equipment.

Competent Person

A person possessing the necessary qualifications, training, and experience to safely undertake designated tasks.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensures adequate resources and systems are in place to implement and maintain this

Authorised Person (HV)

- Performs HV isolations, switching, and issues PTWs.

Hot Work Procedure

Procedure Energy Control Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

This procedure provides clear guidance for the safe management of hot work activities at ACME Mine. It aims to prevent injury, equipment damage, and fire hazards associated with welding, cutting, grinding, and other hot work operations, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Scope

This procedure applies to all personnel, contractors, and visitors undertaking hot work activities within ACME Mine operational areas, including workshops, maintenance bays, processing plants, mobile equipment, and field locations.

3. Definitions

Hot Work

Any activity involving open flames, sparks, or heat generation capable of igniting combustible materials, such as welding, oxy-acetylene cutting, grinding, soldering, brazing, and thermal cutting.

Hot Work Permit

A formal written authorisation issued by an authorised supervisor or delegate, outlining specific controls and conditions required for performing hot work safely.

Fire Watch

A trained and competent person assigned to monitor hot work activities and surrounding areas for potential fire hazards, equipped with suitable firefighting equipment and communication devices.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and training are provided for safe hot work practices.
- Approve and endorse this procedure.

Supervisors

- Issue and authorise Hot Work Permits after assessing hazards and controls.

Workers and Contractors

- Comply with this procedure and conditions outlined in the Hot Work Permit.
- Conduct pre-start checks on equipment and maintain housekeeping standards.
- Cease hot work immediately if unsafe conditions arise and report to supervisor.

Fire Watch Personnel

In-Pit Communications Protocol

Procedure Surface Operations Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear and effective communication protocols for personnel and equipment operating within the pit area at ACME Mine. This ensures operational efficiency, reduces the risk of incidents, and complies with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Scope

This procedure applies to all personnel, contractors, visitors, and equipment operators working within the open-cut pit area at ACME Mine. It covers all forms of communication including radio, verbal, visual, and electronic methods.

3. Definitions

Pit Area

The active mining area where excavation, loading, hauling, and dumping activities occur.

Positive Communication

A clear, confirmed exchange of information between two or more parties, ensuring mutual understanding.

Radio Silence

A period during which radio communications are limited to emergency or critical operational messages only.

Emergency Channel

Designated radio channel reserved exclusively for emergency communications.

Call Sign

Unique identifier assigned to each vehicle, equipment, or personnel for clear identification during radio communication.

4. Roles & Responsibilities

Mine Manager

Ensures adequate resources, training, and compliance with this procedure.

Supervisors

Equipment Operators and Personnel

Adhere to this procedure, maintain clear and concise communication, report communication equipment faults immediately, and participate in training sessions.

Isolation Procedure

Procedure Energy Control Group Effective Date: 21/06/2025 Review Period: 3 Years

1. Purpose

The purpose of this Isolation Procedure is to establish a systematic approach to isolating and controlling energy sources at ACME Mine. This procedure ensures the safety and health of all personnel by preventing unintended energisation, start-up, or release of stored energy during maintenance, servicing, or repair activities, in compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Scope

This procedure applies to all personnel, contractors, and visitors performing tasks requiring isolation of plant, equipment, or machinery at ACME Mine. It covers electrical, mechanical, hydraulic, pneumatic, gravitational, chemical, thermal, and other energy sources.

3. Definitions

Isolation

The process of disconnecting or separating plant, equipment, or machinery from all energy sources to prevent inadvertent energisation or release of energy.

Lockout Device

A device that physically prevents the operation or energisation of equipment, plant, or machinery.

Tagout Device

A clearly marked tag attached to isolation points to warn against operation or energisation.

Authorised Person

An individual who has received appropriate training, instruction, and authorisation to perform isolation tasks.

Stored Energy

Residual energy present in equipment or machinery, such as hydraulic pressure, compressed air, gravitational force, or electrical charge.

4. Roles & Responsibilities

Site Senior Executive (SSE)

Authorised Personnel

Light Vehicle Operation Procedure

Mobile Equipment - Safety and Health Management System Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear guidelines for the safe operation and management of light vehicles at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017. This procedure aims to minimise risks associated with light vehicle operations, protect personnel, and maintain operational efficiency.

2. Scope

This procedure applies to all personnel, contractors, visitors, and authorised operators who operate or travel in light vehicles within the ACME Mine lease area, including haul roads, access roads, workshops, and designated parking areas.

3. Definitions

Light Vehicle

Any vehicle under 4.5 tonnes gross vehicle mass (GVM), including utilities, four-wheel drives, passenger vehicles, and small buses used for transporting personnel, equipment, and materials.

Authorised Operator

A person holding a valid driver's licence, trained, assessed, and authorised by ACME Mine to operate a light vehicle on site.

Pre-start Inspection

A documented inspection conducted prior to vehicle use, identifying any safety or operational issues requiring rectification.

Positive Communication

Clear, confirmed two-way communication between vehicle operators, pedestrians, and mobile equipment operators, ensuring mutual understanding of intended movements.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and systems

Operators and Passengers

- Comply with all requirements outlined in

Light Vehicle Separation Procedure

Surface Operations Effective Date: 21/06/2025 Review Period: 3 Years

1. Purpose

The purpose of this procedure is to establish clear guidelines for the safe separation of light vehicles from heavy mobile equipment and other operational hazards at ACME Mine. This procedure aims to minimise the risk of vehicle collisions, injuries, and fatalities by implementing effective separation measures and controls consistent with the Queensland Coal Mining Safety and Health Act 1999 and Regulation 2017.

2. Scope

This procedure applies to all personnel, contractors, and visitors operating or travelling in light vehicles within the ACME Mine surface operational areas, including haul roads, ramps, workshops, stockpile areas, and other designated operational zones.

3. Definitions

Light Vehicle

Any vehicle under 4.5 tonnes gross vehicle mass (GVM), including utilities, four-wheel drives, sedans, and small buses used for personnel transport or operational support.

Heavy Mobile Equipment (HME)

Mobile plant and equipment exceeding 4.5 tonnes GVM, including haul trucks, excavators, loaders, graders, dozers, water trucks, and drill rigs.

Separation

Physical or procedural measures implemented to maintain safe distances and prevent interaction between light vehicles and heavy mobile equipment.

Positive Communication

Direct two-way radio or visual confirmation between operators to confirm intent, location, and safe passage.

Designated Light Vehicle Routes

Clearly marked and signposted routes specifically established for the exclusive use of light vehicles.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and infrastructure are provided for effective

Operators and Drivers

- Comply with all requirements outlined in this procedure.

Manual Handling Procedure

Type: Procedure SHMS Group: Physical Hazards Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear guidelines for the safe management of manual handling tasks at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017. This procedure aims to prevent musculoskeletal injuries and promote safe manual handling practices across all operational areas.

2. Scope

This procedure applies to all personnel, contractors, and visitors at ACME Mine who undertake or supervise manual handling tasks within the mine site, including workshops, maintenance areas, administration buildings, coal handling preparation plant (CHPP), and mining operational areas.

3. Definitions

Manual Handling

Any activity involving lifting, lowering, pushing, pulling, carrying, moving, holding, or restraining any object, material, or equipment by hand or bodily force.

Musculoskeletal Disorder (MSD)

Injury or illness affecting muscles, nerves, tendons, joints, cartilage, or spinal discs caused by manual handling tasks.

Risk Assessment

A systematic process to identify hazards, evaluate risks, and determine appropriate control measures to reduce or eliminate manual handling risks.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and training are provided to implement effective manual handling controls.
- Approve and endorse this procedure and ensure compliance across the site.

Supervisors

Workers

- Comply with this procedure and participate in manual handling training and risk assessments.
- Report any manual handling hazards, incidents, or injuries promptly to supervisors.
- Utilise provided mechanical aids and follow

Mental Health Support Policy

1. Overview

ACME Mine recognises that mental health is a critical component of overall workforce health, safety, and wellbeing. We are committed to fostering a supportive workplace environment that proactively addresses mental health concerns, reduces stigma, and provides timely and effective support to all employees. This policy aligns with our obligations under the Queensland Coal Mining Safety and Health Act 1999 and the Coal Mining Safety and Health Regulation 2017, ensuring that mental health risks are identified, assessed, and managed appropriately.

2. Key Points

The following principles and actions underpin ACME Mine's approach to mental health support:

Awareness and Education

ACME Mine will promote awareness and understanding of mental health issues through regular communication, toolbox talks, and training sessions, ensuring all employees recognise early signs of mental health concerns and understand available support mechanisms.

Continuous Improvement

The mine will regularly evaluate the effectiveness of mental health support initiatives through employee feedback, incident data analysis, and consultation with workforce representatives, ensuring continuous improvement and responsiveness to workforce needs.

Support Services


Confidential counselling and support services will be made accessible to all employees through an Employee Assistance Program (EAP). Employees and their immediate family members will have access to qualified mental health professionals at no cost.

Leadership Training

Supervisors and managers will receive targeted training to equip them with the skills to recognise signs of mental distress, initiate supportive conversations, and guide employees toward appropriate support services.

Supportive Culture

ACME Mine will actively encourage employees to seek assistance for mental health concerns without fear of discrimination, stigma, or



Misfire Management Procedure

Document Type: Procedure SHMS Group: Drill and Blast Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear guidelines for the safe identification, management, and disposal of misfires during blasting operations at ACME Mine. This procedure ensures compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017, and aims to protect personnel, equipment, and the environment from hazards associated with misfires.

2. Scope

This procedure applies to all personnel involved in drill and blast operations at ACME Mine, including employees, contractors, supervisors, and management. It covers the identification, reporting, investigation, management, and disposal of misfires in all open-cut blasting activities.

3. Definitions

Misfire

A blast or part of a blast that fails to initiate or detonate completely as planned.

Explosives Supervisor

A qualified and competent person appointed to oversee blasting operations and manage explosives safety.

Exclusion Zone

Clearly defined safety perimeter established around blast areas to prevent unauthorised entry during blasting activities.

Shotfirer

A competent and authorised person responsible for the initiation of explosive charges.

Stemming

Inert material placed on top of explosives in a blast hole to confine and direct explosive energy.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and training are provided for misfire management.

Shotfirer

- Identify, report, and manage misfires in accordance with this procedure.

Mobile Equipment Operating Procedure

Safety and Health Management System (SHMS) ACME Mine

Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to establish clear guidelines for the safe operation, inspection, and maintenance of mobile equipment at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017. This procedure aims to minimise risks associated with mobile equipment, ensuring operator safety, equipment integrity, and operational efficiency.

2. Scope

This procedure applies to all personnel, contractors, and visitors involved in the operation, inspection, maintenance, and supervision of mobile equipment within ACME Mine, including haul trucks, excavators, dozers, graders, loaders, water carts, and light vehicles.

3. Definitions

Mobile Equipment

Self-propelled machinery designed for transporting, excavating, loading, grading, or other mining-related activities.

Examples include haul trucks, excavators, loaders, graders, dozers, water carts, and light vehicles.

Operator

A competent person authorised and trained to operate specific mobile equipment.

Pre-start Inspection

A documented inspection of mobile equipment conducted prior to operation to ensure equipment safety and reliability.

Exclusion Zone

Clearly marked area around mobile equipment where unauthorised personnel are prohibited during operation.

Spotter

A trained individual assigned to assist operators by providing guidance during equipment manoeuvres in restricted or congested areas.

Noise and Dust Exposure Management Plan

ACME Mine – Safety and Health Management System (SHMS) Effective Date: 21/06/2025 Review Period: 3 years

1. Objective

The objective of this Noise and Dust Exposure Management Plan is to systematically identify, assess, control, and monitor noise and dust hazards at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999, Coal Mining Safety and Health Regulation 2017, and relevant Australian Standards. This plan aims to protect the health and safety of all mine personnel, contractors, and visitors by minimising exposure to noise and dust hazards.

2. Background

Noise and dust exposure are recognised occupational hazards within open-cut coal mining operations. Prolonged exposure to excessive noise can result in permanent hearing loss, tinnitus, and impaired communication, while prolonged exposure to respirable dust, particularly coal dust and silica, can lead to respiratory diseases such as coal workers' pneumoconiosis (CWP), silicosis, and chronic obstructive pulmonary disease (COPD). ACME Mine conducts various mining activities including drilling, blasting, excavation, haulage, crushing, stockpiling, and maintenance, all of which can generate significant noise and dust emissions. Effective management of these hazards is essential to safeguard the health and wellbeing of our workforce.

3. Key Actions

Risk Assessment

Conduct regular noise and dust risk assessments to identify potential exposure hazards and determine appropriate control measures.

Engineering Controls

Implement engineering controls such as noise attenuation barriers, acoustic enclosures on fixed plant, silencers on mobile equipment, and dust suppression systems (water sprays, dust extraction units, and enclosed conveyors).

Maintenance

Schedule routine maintenance of mobile and fixed plant equipment to minimise noise and dust emissions.

Permit to Work Procedure

Energy Control Group Effective Date: 21/06/2025 Review Period: 3 Years

1. Purpose

The purpose of this procedure is to establish a robust Permit to Work (PTW) system at ACME Mine to ensure hazardous tasks are identified, assessed, authorised, and controlled effectively. This procedure aligns with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017, ensuring the safety and health of all personnel involved in high-risk activities.

2. Scope

This procedure applies to all ACME Mine employees, contractors, and visitors involved in activities requiring a Permit to Work. Activities covered include, but are not limited to:



Working at Heights

Any work conducted at an elevated position where there is potential for a fall.



Confined Space Entry

Work within enclosed or partially enclosed spaces with restricted access/egress and potential atmospheric hazards.



Hot Work

Activities involving welding, cutting, grinding, or other operations producing heat, sparks, or open flames.



High Voltage Electrical Work

Work on or near electrical equipment or installations exceeding 1000V AC or 1500V DC.



Isolation and Energy Control

Activities requiring isolation of energy sources to prevent unexpected energisation or start-up.



Excavation and Trenching

Ground disturbance activities exceeding 300mm in depth.



Hazardous Chemical Handling

Pit Design Compliance Inspection Form

Surface Operations - Safety and Health Management System

Effective Date: 21/06/2025 Review Period: 3 Years

1. Overview

This Pit Design Compliance Inspection Form is designed to ensure that all pit designs and associated mining activities at ACME Mine comply with the Queensland Coal Mining Safety and Health Act 1999, Coal Mining Safety and Health Regulation 2017, and the ACME Mine SHMS. Regular inspections using this form will verify that pit designs are implemented as planned, hazards are effectively controlled, and operational safety standards are maintained.

2. Key Points

Inspectors must verify and document the following key compliance points during each pit design inspection:



Pit Wall and Bench Design

Pit walls and benches are constructed and maintained according to approved geotechnical and engineering designs.



Geometric Parameters

Bench heights, widths, and slope angles conform to the approved pit design parameters.



Water Management

Adequate drainage and water management controls are implemented and maintained to prevent slope instability and erosion.



Haul Road Design

Haul roads and ramps are constructed to approved gradients, widths, and safety berm specifications.



Pit Floor Conditions

Pit floor conditions are maintained to ensure safe equipment operation and personnel access.



Hazard Identification

Rostering and Shift Limits Procedure

Human Factors SHMS Group Effective Date: 21/06/2025 Review Period: 3 Years

1. Purpose

The purpose of this procedure is to establish clear guidelines for rostering and shift limits at ACME Mine, ensuring compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017. This procedure aims to manage fatigue and associated risks, promoting the health, safety, and wellbeing of all personnel.

2. Scope

This procedure applies to all ACME Mine employees, contractors, and visitors involved in operational activities on-site, including production, maintenance, supervisory, and support personnel.

3. Definitions

Fatigue

A state of impaired physical or mental performance resulting from inadequate rest, excessive workload, or extended periods of wakefulness.

Roster

A planned schedule detailing shift patterns, working hours, and rest periods.

Shift

A defined period of work, typically 8 to 12 hours, during which personnel perform assigned tasks.

Shift Limit

Maximum allowable working hours per shift and per roster cycle, designed to minimise fatigue risks.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Approve and oversee implementation of rostering and shift limits procedure.
- Ensure resources are available to manage fatigue risks effectively.

Supervisors and Managers

Workers (Employees and Contractors)

- Comply with rostered shift limits and rest periods.
- Report fatigue-related concerns immediately to supervisors.
- Ensure personal lifestyle choices support

Scaffold and Edge Protection Checklist

Frequency of Use: This checklist must be completed prior to initial use of scaffolding or edge protection systems, weekly thereafter, and immediately following any alterations, adverse weather events, or incidents involving the scaffold or edge protection.

Inspection Items:

1 Scaffold Structure

- Scaffold erected on stable and level ground with adequate foundations.
- Scaffold components free from visible damage, corrosion, or defects.
- Scaffold erected according to manufacturer's specifications and certified design.
- Scaffold fully braced and secured to prevent movement or collapse.
- Scaffold platforms fully decked, secured, and free from trip hazards.
- Safe access and egress points provided and clearly identified.

2 Edge Protection

- Edge protection installed at all open edges where there is a risk of falling.
- Guardrails, mid-rails, and toe boards securely fitted and in good condition.
- Edge protection systems meet minimum height and strength requirements.
- Mesh or screens installed where required to prevent falling objects.

3 Signage and Tagging

- Scaffold clearly tagged with current inspection status (safe to use or do not use).
- Appropriate signage displayed indicating safe working loads and restrictions.

4 Housekeeping and Environment

- Scaffold platforms clear of debris, tools, and materials.
- Adequate lighting provided for safe access and working conditions.
- Scaffold and edge protection free from environmental hazards (e.g., mud, ice, water accumulation).

5 Documentation and Records

- Scaffold erection and inspection records available and current.
- Competency records for scaffold erectors and inspectors available and verified.

Action Required if Not Compliant:

Shotfirer Role Description

Template

When to Use

This Shotfirer Role Description Template is to be utilised when defining and documenting the responsibilities, competencies, and accountabilities of personnel appointed to the position of Shotfirer at ACME Mine. It ensures clarity of role expectations, compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017, and alignment with the mine's Safety and Health Management System (SHMS).

Instructions for Use

1. Review the template and ensure it aligns with current operational practices, legislative requirements, and the mine's SHMS.
2. Complete all sections clearly, accurately reflecting the specific duties, responsibilities, and competencies required for the Shotfirer role at ACME Mine.
3. Engage relevant stakeholders, including Drill and Blast Supervisors, Training Coordinators, and Safety Advisors, to confirm accuracy and completeness of the role description.
4. Obtain formal approval from the Drill and Blast Superintendent and the Site Senior Executive (SSE) prior to implementation.
5. Communicate and distribute the approved role description to relevant personnel and maintain a controlled copy within the SHMS documentation system.
6. Review and update the role description every three years or sooner if operational changes or legislative amendments occur.

Example Entries

Position Title: Shotfirer

Reporting to: Drill and Blast Supervisor

Role Purpose: To safely and effectively plan, prepare, load, and fire explosive charges in accordance with the mine's SHMS, operational plans, and legislative requirements.

Key Responsibilities:



Risk Management

Conduct pre-blast risk assessments and inspections of blast areas to identify and control hazards.

Tagging and Lockout Policy

Energy Control Group Effective Date: 21/06/2025 Review Period: 3 years

1. Overview

ACME Mine is committed to ensuring the safety and health of all personnel through effective energy isolation practices. This Tagging and Lockout Policy outlines mandatory requirements for isolating, tagging, and locking out plant, equipment, and energy sources to prevent inadvertent activation or energisation during maintenance, servicing, or repair activities. Compliance with this policy ensures alignment with the Queensland Coal Mining Safety and Health Act 1999 and the Coal Mining Safety and Health Regulation 2017, specifically addressing the management of energy isolation risks.

2. Key Points

All personnel at ACME Mine must adhere to the following requirements:



Energy Isolation

Prior to commencing any maintenance, servicing, or repair work on plant or equipment, authorised personnel must isolate all relevant energy sources, including electrical, mechanical, hydraulic, pneumatic, gravitational, and stored energy.



Lockout and Tagging

Isolation points must be clearly identified, tagged, and secured using approved lockout devices. Tags must clearly display the name, date, contact details, and reason for isolation.



Personal Locks

Each worker involved in the task must apply their personal lock and tag to the isolation point(s). Personal locks must be individually keyed, with only one key issued to the lock holder.



Group Isolation

Group isolation procedures must be implemented where multiple personnel are involved. A clearly identified group lockbox or multi-lock hasp must be used, and each worker must attach their personal lock and tag to the group isolation device.



Lock Removal

Only the person who applied the lock and tag is authorised to remove it. In exceptional circumstances, if the lock owner is unavailable, the lock may be removed only after obtaining written approval from the Site Senior Executive (SSE) or authorised delegate,

Traffic Management Plan

Surface Operations Effective Date: 21/06/2025 Review Period: 3 years

1. Objective

The objective of this Traffic Management Plan is to establish clear guidelines and controls for managing vehicle and pedestrian movements within ACME Mine operations. This plan aims to minimise risks associated with vehicle interactions, collisions, pedestrian safety, and to ensure compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Background

ACME Mine is an open-cut coal operation involving extensive mobile equipment movements, including haul trucks, excavators, loaders, graders, water carts, and light vehicles. The complexity of vehicle interactions, combined with pedestrian movements, presents significant safety risks. Effective traffic management is essential to prevent incidents, injuries, and fatalities arising from vehicle collisions, rollovers, or pedestrian interactions.

3. Key Actions



Road Design and Signage

Clearly defined and signposted haul roads, access roads, intersections, and pedestrian crossings.



Speed Management

Implementation of designated speed limits across all operational areas, clearly displayed and enforced (e.g., 60 km/h on main haul roads, 40 km/h on ramps, and 10 km/h in workshop and pedestrian areas).



Traffic Control Devices

Installation and maintenance of traffic control devices, including signage, delineators, reflective markers, and barriers.



Pedestrian Management

Establishment of segregated pedestrian walkways and clearly marked pedestrian crossings in operational areas, workshops, and administration zones.



Vehicle Safety Features

UV and Heat Stress Management Plan

ACME Mine Effective Date: 21/06/2025 Review Period: 3 years

1. Objective

The objective of this UV and Heat Stress Management Plan is to ensure the health and safety of all ACME Mine personnel by systematically identifying, assessing, and controlling risks associated with exposure to ultraviolet (UV) radiation and heat stress. This plan aligns with the Queensland Coal Mining Safety and Health Act 1999 and the Coal Mining Safety and Health Regulation 2017, ensuring compliance and best practice management of physical hazards.

2. Background

ACME Mine is an open-cut coal mining operation located in Queensland, where employees regularly perform tasks outdoors, often under conditions of high ambient temperatures and intense solar radiation. Exposure to UV radiation and heat stress can lead to serious health conditions including sunburn, heat exhaustion, heat stroke, dehydration, skin cancer, and eye damage. Effective management of these hazards is essential to maintaining workforce health, productivity, and compliance with legislative requirements.

3. Key Actions



Risk Assessment

Conduct regular risk assessments to identify tasks, roles, and areas where workers are exposed to UV radiation and heat stress.



Engineering Controls

Implement engineering controls such as shade structures, air-conditioned cabins in mobile equipment, and adequate ventilation in fixed plant areas.



Work Scheduling

Schedule outdoor work activities to minimise exposure during peak UV radiation and heat periods, typically between 10:00 am and 3:00 pm.



Personal Protective Equipment

Provide appropriate personal protective equipment (PPE), including wide-brimmed hats, UV-rated safety glasses, long-sleeved high-visibility clothing, sunscreen (minimum SPF 50+), and adequate water supply.



Hydration

Working at Heights Procedure

Procedure - Physical Hazards Effective Date: 21/06/2025 Review Period: 3 years

1. Purpose

The purpose of this procedure is to outline the mandatory requirements and safe work practices for managing risks associated with working at heights at ACME Mine. This procedure ensures compliance with the Queensland Coal Mining Safety and Health Act 1999, Coal Mining Safety and Health Regulation 2017, and relevant Australian Standards, aiming to prevent falls and associated injuries.

2. Scope

This procedure applies to all personnel, contractors, and visitors performing tasks at ACME Mine where there is a risk of falling from one level to another, including but not limited to maintenance activities, inspections, construction, equipment servicing, and any other tasks involving elevated work platforms, scaffolding, ladders, or other height-related equipment.

3. Definitions

Working at Heights

Any task performed at a height of two metres or more above ground level or where a person could fall into an opening or excavation.

Fall Arrest System

Equipment designed to safely arrest a fall, including harnesses, lanyards, anchor points, and energy absorbers.

Fall Restraint System

Equipment designed to prevent a person from reaching a position where a fall could occur.

Elevated Work Platform (EWP)

A mechanical device used to provide temporary access for personnel or equipment to elevated locations.

Competent Person

An individual who has acquired through training, qualification, or experience the knowledge and skills to safely perform tasks associated with working at heights.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and systems

Workers and Contractors

- Comply with this procedure and relevant

Working Near Crests and Slopes

Procedure

1. Purpose

The purpose of this procedure is to establish clear guidelines and controls for managing risks associated with working near crests and slopes at ACME Mine. This procedure aims to prevent incidents related to ground instability, slope failure, and vehicle or equipment rollover, ensuring the safety and health of all personnel and compliance with the Queensland Coal Mining Safety and Health Act 1999 and Coal Mining Safety and Health Regulation 2017.

2. Scope

This procedure applies to all personnel, contractors, and visitors working or operating vehicles and equipment near crests, slopes, benches, dumps, stockpiles, and excavations within the operational boundaries of ACME Mine.

3. Definitions

Crest

The uppermost edge of a slope, bench, or excavation.

Slope

An inclined surface of ground, excavation, or stockpile, including highwalls, low walls, spoil dumps, and ramps.

Exclusion Zone

Clearly demarcated areas established to restrict access near crests or slopes due to identified geotechnical hazards.

Geotechnical Hazard

A hazard arising from geological or ground conditions, including instability, erosion, subsidence, or slope failure.

TARP (Trigger Action Response Plan)

A documented plan outlining specific actions and responses triggered by identified geotechnical conditions or events.

4. Roles & Responsibilities

Site Senior Executive (SSE)

- Ensure adequate resources and systems are provided to manage geotechnical

Supervisors

- Ensure personnel under their supervision are trained and competent in this