



Release gate

The visual concept is complete for hierarchy review. Structural production work remains blocked.

PRODUCTION RELEASE: BLOCKED

Reason: no manufacturer dieline, verified panel geometry, bleed, fold map or safe-area specification is available.

CONCEPT-SAFE WORK

- Use only the supplied brand, product name and net contents.
- Review the visual tone, type hierarchy, palette and motif.
- Maintain a geometry-neutral content inventory.
- Prepare the manufacturer request and release checklist.

PRODUCTION-BLOCKED WORK

- Assign artwork or legal copy to panels.
- Build cut, crease, fold, flap or glue layers.
- Extend backgrounds into bleed or across seams.
- Set barcodes, variable data or finishing masks.
- Export any file as print ready or factory ready.

ASSUMPTION REGISTER

Package geometry	None assumed
Panel count or proportions	None assumed
Bleed / folds / safe areas	None assumed
Concept rectangle	Illustrative content card only; it has no production scale
Production units	Not established

COPY AVAILABLE TO THIS WORKFLOW

Approved visible strings	North Field / Herbal Balm / Net 60 g
Unavailable verbatim text	Ingredients and warnings are referenced by the brief, but their exact wording is not present in the accessible input.



Missing structural parameters

All items below are missing. No numeric value, contour or panel assignment has been inferred.

16 OPEN STRUCTURAL INPUTS

S01 Manufacturer dieline file

Need: Dimensioned 1:1 vector file, units, revision/date and approved source.

S02 Carton construction

Need: ECMA/FEFCO code or explicit style; closure and opening direction.

S03 Finished internal size

Need: W x D x H in mm, dimension convention and dimensional tolerances.

S04 Panel map

Need: Identity, width, height and reading orientation for every body panel.

S05 Cut contour

Need: Exact vector path including radii, notches, slots and external cut edges.

S06 Creases and folds

Need: Centerlines, fold direction, score type and assembly sequence.

S07 Flap geometry

Need: Glue, tuck, dust and lock flap dimensions, angles and overlaps.

S08 Adhesive zones

Need: Glue coverage, seam overlap and no-ink / no-varnish keep-outs.

S09 Bleed

Need: Required mm beyond each cut edge and rules for seams / internal cutouts.

S10 Safe areas

Need: Required inset from cuts, creases, perms, slots and glue by panel.

S11 Substrate

Need: Board grade, thickness/caliper, coating and grain direction.

S12 Manufacturing tolerances

Need: Allowed cut, crease, register, glue and assembly variation.

S13 Special structures

Need: Any perforation, tear strip, window, hang tab or locking feature geometry.

S14 Finishing geometry

Need: Any foil, spot coating, white ink, emboss/deboss mask and keep-outs.

S15 File setup

Need: Units, scale, page box, required layers, dieline colors/weights and non-print rules.

S16 Wrap and seam behavior

Need: Cross-panel continuity, seam allowance and assembled reading direction.

ACCEPTABLE SOURCE: MANUFACTURER-APPROVED DIELINE OR APPROVED MEASURED PROTOTYPE



Acquisition, proof and approval

Preferred path: obtain a manufacturer-approved dieline. Derivation is permitted only through measured engineering and physical validation.

A / REQUEST FROM MANUFACTURER

- Supply the S01-S16 inputs on page 2, with a named revision and contact owner.
- Confirm whether the dieline is inside view or outside print view and identify every panel.
- Confirm print process, color/ICC profile, inks, trapping/overprint, image resolution, total ink and minimum type/line rules.
- Provide the proofing standard and required prepress submission format.

B / DERIVE ONLY IF NO APPROVED DIELINE EXISTS

- Obtain an assembled blank, an unglued flat blank, the actual product and a calibrated measuring tool.
- A packaging engineer records all S01-S16 values and creates a 1:1 measured drawing with revision control.
- The resulting drawing remains provisional until the manufacturer approves it in writing and the sample test passes.

REQUIRED 100% SAMPLE TEST

- 1 Output at 100% with no scaling on the specified stock/caliper.
- 2 Cut, crease, glue and assemble using the verified production sequence.
- 3 Insert the actual filled 60 g product; verify fit, closure, opening and glue integrity.
- 4 Check every critical mark against cut, crease, perforation, slot, seam and adhesive zones.
- 5 Verify bleed and cross-panel continuity; scan barcode and inspect variable data if applicable.
- 6 Record photos, measured results, deviations and written manufacturer/client approval.

RELEASE APPROVALS

Required: client concept approval; regulatory approval of exact copy; manufacturer/prepress approval of geometry and print specs; passing physical sample; final client artwork approval.