Millbrook Collision Center

1880 Industrial Blvd, Millbrook, VA 23990 | (804) 555-0161

PRELIMINARY REPAIR ESTIMATE
No. RO-26-4471
Date: 2026-10-30

Customer	Marcus Bell
Vehicle / Property	2019 Toyota Camry SE | VIN 4T1B11HK5KU238810 | 61,400 mi

#	Description	Qty	Unit	Unit price	Amount
1	Rear bumper cover (OEM)	1	ea	$418.00	$418.00
2	Rear bumper energy absorber	1	ea	$96.00	$96.00
3	Rear bumper reinforcement bar	1	ea	$286.00	$286.00
4	Tail lamp assembly, left	1	ea	$214.00	$214.00
5	Rear parking sensor	1	ea	$168.00	$168.00
6	Body labor - R&I rear bumper, replace cover & reinforcement	3.2	hr	$58.00	$185.60
7	Body labor - repair rear body panel (minor)	1.8	hr	$58.00	$104.40
8	Body labor - transfer sensors & brackets	0.8	hr	$58.00	$46.40
9	Refinish labor - bumper cover, blend quarter panels	4.1	hr	$58.00	$237.80
10	Paint & materials	4.1	hr	$39.00	$159.90
11	Hazardous waste disposal	1	ea	$28.00	$28.00
	TOTAL				**$1,944.10**

Notes / Findings

Impact to rear center/left. Bumper cover cracked, reinforcement bent, LT tail lamp lens broken, center parking sensor inoperative. No structural damage observed.

Prices valid 30 days. Hidden damage may require a supplement. Payment is the responsibility of the customer unless the insurer has authorized direct payment in writing.