

# Standard Operating Procedure for Resolving Minor Alarm ALARM\_5594 on Arista Access Switch

**Node:** Arista-Access-Bangalore-KA-72 | **Vendor:** Arista | **Severity:** Minor | **Alarm Code:** ALARM\_5594

## Description

This SOP outlines the steps to diagnose and resolve minor alarm ALARM\_5594 on Arista Access Switch Arista-Access-Bangalore-KA-72.

## Potential Root Causes

| Cause                                                     | Probability |
|-----------------------------------------------------------|-------------|
| High CPU utilization due to software bugs or high traffic | High        |
| Misconfigured interface or VLAN settings                  | Medium      |
| Hardware issues with the interface or switch              | Low         |

## Diagnostic Commands

```
show system resource cpu
show interface
show vlan
show spanning-tree
```

## Resolution Steps

- Step 1: {'Step': 'Check CPU utilization and system logs for any errors or issues', 'Action': 'show system resource cpu | show system log'}
- Step 2: {'Step': 'Verify interface and VLAN settings', 'Action': 'show interface | show vlan'}
- Step 3: {'Step': 'Clear counters and check for any errors', 'Action': 'clear counters | show interface'}
- Step 4: {'Step': 'If hardware issues suspected, perform a hardware check and replace if necessary', 'Action': 'Perform hardware check | Replace hardware if necessary'}

## Post-Check Verification

```
show interface
show vlan
show system log
```